

**HUDSON MOTOR CAR COMPANY
PARTS PRICES AND PARTS SPECIFICATIONS**

1935 SERIES BULLETINS

INDEX

<u>NO.</u>	<u>DATE</u>	<u>SUBJECT</u>
2	12/17/34	Water Pump Packing.
3	1/ 8/35	Monroe Shock Absorber Valves - Starting Part Numbers Electric Hand Cross Shift Switch Change.
4	1/22/35	Steering Wheel Substitutions - Correction 1933 Parts Book.
5	1/22/35	Packaged Parts.
7	2/19/35	Brake Lining.
8	5/ 6/35	Spring Details - Explanation of Car Serial Numbers.
9	3/27/35	Clutch Vacuum Control Cables - Parts Books Corrections.
10	4/ 3/35	1935 Parts Book Revisions - Brakes - Hand Brake - Drag Link - Springs.
10-A	6/ 7/35	1935 Parts Book Revisions - Battery - Generator - Differential - Drive Shaft - Wheel Bearings - Clutch.
10-B	6/14/35	1935 Parts Book Revisions - Hard Brake - Frame - Throttle Control - Radiator - Coil - Switches.
10-C	7/ 2/35	1935 Parts Book Revisions - Carburetor and Fuel Pump - Clutch Vacuum Control - Wiring - Generator.
10-E	7/30/35	Parts Book Revisions - Manifold Gaskets - Springs - Battery - Radio Antenna.
10-F	7/30 /35	Parts Book Revisions -Springs - Frame - Coil - Radio and Antenna.
11	4/ 4/35	1935 Parts Price List.
12	4/18/35	Parts Price Changes.
13	5/ 1/35	Painted Parts - Terraplane Special Coach Passenger Seat - Parts Book Corrections.
14	5 /27/35	Parts Price Changes
15	6/ 7/35	Confidential Net Price List - 1935 Body Parts Book.
16	6/10/35	Parts Price Changes.
17	6/17/35	Wheel Hubs and Drums - Stabilizer Kit - Drive Gear and Pinion Substitution Discontinued.
18	6/20/35	Parts Price Changes.
19	7/ 2/35	Locks - Corrections to Parts Books.
20	8/19/35	Parts Price Changes.
21	8/25/35	Windshield Cleaner - Parts Book Corrections - Special Clutch.
22	8/23/35	New Wire Code Words
24	11/11/35	Index of 1935 Series Parts Prices and Specifications

**HUDSON MOTOR CAR COMPANY
PARTS PRICES AND PARTS SPECIFICATIONS
1935 SERIES BULLETINS**

No. 2
Date 12/17/34
Subject

Form 8103

TO ALL DEALERS:

In checking the car for winter driving and in the inspection during cold weather and in the periodic inspection during cold weather, an important matter is of leaks in the cooling system. This is especially true, of course, in northern where loss of anti-freeze solution is a serious consideration. The water pump shaft, packing must be in good condition at all times in order to prevent leaks at this point. The Service packing supplied by the factory is the best on the market, and may be installed without the necessity of dismantling the pump, or of removing the old packing.

In order that you may take full advantage of demand for this item, we have established a new list price, subject to regular discounts, to be effective as of December 15, 1934.

Part No.	List Price	Name
BM 45277	.10	Water Pump Packing

Make this correction in your Numerical Price List and cancel the item from the Confidential Net Price List.

P. E. Jones
Supervisor,
Parts and Specifications Division
Service Department.

WATER
PUMP
PACKING

HUDSON MOTOR CAR COMPANY

PARTS PRICES AND PARTS SPECIFICATIONS

1935 SERIES BULLETINS

No. 3
 Date 1/8/35
 Subject

Form 8103

TO ALL DEALERS:

In order to vary the control of the Monroe Shock Absorbers on the 1935 Terraplane cars, it is necessary to replace the Piston and Valve Assembly. Those Assemblies for Standard, Heavy, and Light Control are listed below:

BZ 47740	Piston and Valve Assembly-Front)	Standard Control
BZ 47741	Piston and Valve Assembly-Rear)	Standard Control
BZ 47742	Piston and Valve Assembly-Front)	Heavy Control
BZ 47743	Piston and Valve Assembly-Rear)	Heavy Control
BZ 47744	Piston and Valve Assembly-Front)	Light Control
BZ 47745	Piston and Valve Assembly-Rear)	Light Control

TERRAPLANE
SHOCK
ABSORBERS

In the case of Spicer Shock Absorbers on the 1935 Hudson cars, the control is varied by changing the valve plate only. Valve plates for the different controls are as follows:

BZ 47746	Valve Plate-Front (Stamped #10)	Standard Control
BZ 46026	Valve Plate-Rear (Stamped # 7)	Standard Control
BZ 47747	Valve Plate-Front (Stamped #11)	Heavy Control
BZ 47748	Valve Plate-Rear (Stamped # 8)	Heavy Control
BZ 47748	Valve Plate-Front (Stamped # 8)	Light Control
BZ 46028	Valve Plate-Rear (Stamped -# 6)	Light Control

HUDSON
SHOCK
ABSORBERS

It may be of benefit in arranging your stock room set-up to know the starting points of parts symbol number series for each year. Compiled for the last three years, these are as follows:

1933

Chassis Parts start at 42000
 Body Parts start at 101400
 Trim Parts start at106000

1934

Chassis Starts start at 44500
 Body Parts start at 107000
 Trim Parts start at 110000

1935

Chassis Parts start at 47000
 Body Parts start at 112000
 Trim Parts start at 113400

PARTS
SYMBOL
NUMBER

(OVER)


ERRATA

On page 12 of the Preliminary List of 1935 Non-Interchangeable parts, the Antenna and Support, Assembly (BO 47471) appears as a serviceable item carrying a list price of \$1.25.

This Is an error, and this item should be deleted, as well as the item immediately following namely, BO 47472 - as these cannot be supplied separately.

The electrical characteristics of the antenna system have been adjusted to the radio circuit, and for this reason, the only way in which we can supply the antenna is as a complete assembly including the lead-in wire and shield. This Assembly carries symbol number BO 47423 and has a list price of \$5.00, subject to usual discounts. It includes the complete aerial installation with attaching screws.

Please make this correction in your list.



ELECTRIC
HAND

We call to your attention the fact that a change has been made in the method of operating the Cross-Shift Switch to provide a slip joint connection between rod and switch lever. This necessitates a new symbol number for the Switch Assembly; also the release of two new parts. The switch rod retains the same symbol, but has been altered to increase the length of threaded portion from 1-1/8" to 1-7/8". Symbol numbers are as follows:

	Old No	New No.
Cross-Shift Switch Assembly	47313	47941
Cross-Shift Switch Rod (threaded length 1-1/8")	47314	
Cross-Shift Switch Rod (threaded length 1-7/8")		47314
Cross-Shift Switch Rod Tapped Sleeve		47945
Cross-Shift Switch Rod Special Nut		47946

If it becomes necessary to replace the first type switch for any purpose, use one 47944 Switch Assembly, one 47945 tapped sleeve, and one 47946 special nut. Also run the threads down on the switch rod to a length of 1-7/8" or use a new 47314 rod with 1-7/8" threaded length. Instructions for adjustment of the tapped sleeve will be found on 1935 Reference Sheet #3.

P. E. Jones

Parts Specifications Division,
Service Department.

**HUDSON MOTOR CAR COMPANY
PARTS PRICES AND PARTS SPECIFICATIONS
1935 SERIES BULLETINS**

Form 8103

No. 4
Date 1/22/35
Subject

TO ALL DEALERS:

Please be advised that our stock of Steering Wheel Assembly, C 40043, is exhausted and will no longer be supplied. Substitutions will be made as follows:

Use C 47222 for 1932-1933-1934	Terraplane K
1933-1934	Terraplane KU
1933	Terraplane KT
C 47223 for 1934	Hudson LT and LL

Also our stock is exhausted on Steering Gear Complete, C 46062, which will not be supplied in the future. The following substitutions will be made:

Use C 47224 for 1934	Terraplane K and KU
C 47225 for 1934	Hudson LT

For a permanent record, these substitutions as well as any of which you are notified in the future, should be immediately noted in the parts book covering the models involved.

Your attention is called to an error on Page 11 of the December Terraplane Parts List. Under the heading "Brakes - Rear", BY 43369 and BY 43370 are listed as Backing Plate Assembly - R.H. and L.H., respectively. The description should be reversed to read as follows:

BY 43369	BACKING PLATE ASSEMBLY - L.H.
BY 43370	BACKING PLATE ASSEMBLY - R.H.

P. E. Jones

Supervisor,
Parts Specifications Division,
Service Department

SUBSTITUTION

CORRECTION

HUDSON MOTOR CAR COMPANY

PARTS PRICES AND PARTS SPECIFICATIONS

1935 SERIES BULLETINS

No. 5

Date 1/22/35

Form 8103

Subject

TO ALL DEALERS:

The convenience of ordering and storing parts in unit packages is well known to you. We list below those items which we are prepared to supply in unit packages, with the quantity of each item per box, and urge that they be ordered accordingly.

<u>Part No.</u>	<u>Name</u>	<u>Quantity</u> <u>Per Box</u>	<u>Part No.</u>	<u>Name</u>	<u>Quantity</u> <u>Per Box</u>
2655	Gasket	10	33290	Hub Cap	5
13041	Valve	10	33331	Piston Ring	10
19322	Gasket	10	33448	Hub Cap	2
22702	Piston Pin	10	33470	Lens	5
22779	Gasket	10	35009	Piston Ring	10
23251	Gasket	10	35022	Piston Ring	20
23622	Gasket	10	35024	Piston Ring	20
23627	Chain	1	33026	Piston Ring	20
25886	Pivot Pin	5	35081	Gasket	10
28014	Lens	2	35183	Gasket	10
28667	Lens	2	35384	Hub Cap	5
28954	Pivot Pin	5	35918	Cork Gasket	5
29013	Gasket	10	36334	Gasket	100
29029	Valve	10	38505	Gasket	10
29075	Hub Cap	5	37029	Piston Ring	10
29076	Hub Cap	5	37031	Piston Ring	20
29361	Gasket	10	37048	Valve	10
29363	Gasket	20	37049	Valve	10
29863	Gasket	5	37144	Gasket	10
29903	Valve	10	37223	Gasket	10
29904	Valve	10	37255	Gasket	10
29909	Gasket	20	37861	Hub Cap	2
29910	Gasket	20	37882	Hub	2
30391	Cork Gasket	5	40154	Gasket	10
30393	Lens	2	40999	Hub Cap	2
30440	Gasket	5	42038	Gasket	5
30913	Lens	2	42342	Hub Cap	2
31082	Hub Cap	5	42792	Hub Cap	2
31251	Hub Cap	5	43443	Piston Ring	20
31263	Gasket	10	43445	Piston Ring	20
32119	Piston Ring	20	43447	Piston Ring	20
33094	Valve	10	43452	Piston Ring	20
33096	Gasket	10	43454	Piston Ring	20
33149	Piston Ring	20	43456	Piston Ring	120
33156	Gasket	10	44612	Valve	10
33171	Gasket	20	44613	Valve	10
33173	Gasket	10	44621	Gasket	10

PARTS CARRIED
IN UNIT
PACKAGES

(OVER)

PARTS CARRIED
IN UNIT
PACKAGES

<u>Part No.</u>	<u>Name</u>	<u>Quantity Per Box</u>	<u>Part No.</u>	<u>Name</u>	<u>Quantity Per Box</u>
33176	Gasket	10	44628	Gasket	10
33190	Gasket	20	44734	Gasket	10
44779	Gasket	10	63190	Pivot Pin	10
45003	Hub Cap	2	63514	Lens	2
45004	Hub Cap	2	63527	Gasket	10
45005	Hub Cap	2	63534	Piston Ring	20
45733	Hub Cap	2	63551	Gasket	20
45739	Radio Control		63552	Gasket	20
	Bezel	2	63584	Hub Cap	5
47097	Piston	6	63797	Valve	10
47117	Gasket	10	64271	Pivot Pin	10
47118	Casket	10	65018	Gasket	10
57313	Lens	2	65040	Gasket	10
60027	Gasket	10	65303	Hub Cap	5
60038	Gasket	10	65578	Lens	2
60315	Gasket	10	65588	Cork Gasket	5
60336	Piston Ring	20	65800	Piston Ring	20
61489	Pivot Pin	10	65896	Piston Ring	20
61615	Gasket	10 - 20	96105	Glass	2
61622	Gasket	10	96198	Lens	2
61993	Lens	2	96199	Cork Gasket	5
61994	Cork Gasket	5	99350	Glass	2
62078	Gasket	10	102571	Lens	2
62079	Gasket	10	109261	Lens	2 - 5
62103	Piston Ring	20	109262	Lens	2 - 5
62290	Gasket	10	109276	Lens	2 - 5
62356	Hub Cap	5	109277	Lens	2 - 5
62544	Gasket	10	109278	Gasket	5
62552	Gasket	10	111214	Trunk Irons	2
62554	Gasket	10	114476	Lens	2
62618	Lens	2	114477	Lens	2
62710	Pivot Pin	10			

W. D. Morgan

Superintendent,
Parts Department

HUDSON MOTOR CAR COMPANY

PARTS PRICES AND PARTS SPECIFICATIONS

1935 SERIES BULLETINS

No. 7

Date 2/19/35

Form 8103

Subject

TO ALL DEALERS:

Hycoe moulding lining has replaced Marshall lining on the Primary Shoes only of front brakes on all 1935 models. This necessitates a change of symbol numbers on the following parts:

BRAKE LINING

BX 48123 - FRONT BRAKE SHOES AND LINING ASSEMBLY For 1935 Terraplane	Supersedes 47394
BX 48124 - FRONT BRAKE SHOES AND LINING ASSEMBLY For Hudson Six - Special and Deluxe Eight	Supersedes 47395
BX 48125 - FRONT BRAKE SHOES AND LINING ASSEMBLY For Hudson Custom Eight	Supersedes 47599
F 48132 - Brake Shoes Lining Package For Terraplane and Utility Coach	Supersedes 46810
F 48133 - Brake Shoes Lining Package For Terraplane Commercial (Except Utility Coach)	Supersedes 46801
F 48134 - Brake Shoes Lining Package For Hudson Six - Special and Deluxe Eight	Supersedes 46798
F 48135 - Brake Shoes Lining Package For Hudson Custom Eight	Supersedes 46811

This change took place with the following car numbers:

Terraplane Special	51717	Hudson Special Eight	54458
Terraplane Deluxe	52501	Hudson Deluxe Eight	55214
Hudson Six	53330	Hudson Custom Eight	56183

- - - - -

Hycoe lining also replaces Marshall lining on the Primary Shoes of Rear Brakes on the Hudson Custom Eight, effective with car No. 56767. The following part numbers are affected:

BX 48125 - FRONT BRAKE SHOES AND LINING ASSEMBLY For Hudson Custom Eight	Supersedes 47599
F 48245 - Brake Shoes Lining Package For Hudson Custom Eight	Supersedes 46811

The Marshall listing continues in use on the secondary shoes of front and rear brakes of all models, and on primary shoes of rear brakes of all models except the Hudson Custom Eight.

(OVER)

Care should be taken to see that replacements of Brake Shoes Assemblies are made in pairs only. Old and new type assemblies should not be mixed on right and left sides of car. For identification, both edges of the Hycoe lining are painted white.

P. E. Jones,
Supervisor,
Parts Specifications Division,
Service Department.

HUDSON MOTOR CAR COMPANY

PARTS PRICES AND PARTS SPECIFICATIONS

1935 SERIES BULLETINS

No. 8

Date 3/6/35

Form 8103

Subject

TO ALL DEALERS:

We give below a list of leaves, canter bolts and clips used on the various springs in 1935 production. This is to supplement information on pages 18 and 19 of the 1935 Chassis Parts Book.

SPRING
DETAILS

Spring Assy.	F 45280	47208	47209	47215	46473	47216	45284	47217
Rebound Leaf	<u>Front</u>	<u>Front</u>	<u>Front</u>	<u>Rear</u>	<u>Rear</u>	<u>Rear</u>	<u>Rear</u>	<u>Rear</u>
				C 43644	43644	43644	43644	45693
#1 Main Leaf	C 45656	48260	48260	45678	45678	45678	45678	45694
#2 Leaf	C 45657	48261	48261	45679	45679	45679	45679	45695
#3 Leaf	C 45658	48262	48268	45680	45680	45687	45687	45696
#4 Leaf	C 45659	48263	48269	45681	45681	45688	45688	46217
#5 Leaf	C 45660	48264	48270	45682	45682	45689	45689	46218
#6 Leaf	C 45661	48265	48271	45683	45683	45690	45690	46219
#7 Leaf	C 45662	48266	48272	45684	45684	45691	45691	46220
#8 Leaf	C 45663	48267	48273	45685	45685	45692	45692	46221
#9 Leaf			C 48267	45686	45686			46222
#10 Leaf								C 43790
Center Bolt Assembly	BZ 46205	46205	46206	46208	46208	45307	45307	36209
Clips #1 (Clinch)	BZ 46211	40887	46211	40890	40890	40890	40890	40890
Clips #2 (Bolted)	BZ 46212	48319	46212	46213	46213	46213	46213	46215
Clip #3 (Bolted)				BZ 46214	46214	46214	46214	46216
Clip #4 (Band Eye)				BZ 43342	43642	43642	43642	43642
Clip Bolt	<u>#2</u>	<u>#2</u>	<u>#2</u>	<u>#2&3</u>	<u>#2&3</u>	<u>#2&3</u>	<u>#2&3</u>	<u>#2&3</u>
	BZ 46204	46204	46204	46204	46204	46204	46204	46204
Clip Bolt				<u>#4</u>	<u>#4</u>	<u>#4</u>	<u>#4</u>	<u>#4</u>
				BZ 43643	43643	43643	43643	43643
Clip Bolt Nut	<u>#2</u>	<u>#2</u>	<u>#2</u>	<u>#2&3</u>	<u>#2&3</u>	<u>#2&3</u>	<u>#2&3</u>	<u>#2&3</u>
	BZ 18045	18045	18045	18045	18045	18045	18045	18045
Clip Bolt Nut				<u>#4</u>	<u>#4</u>	<u>#4</u>	<u>#4</u>	<u>#4</u>
				BZ 5402	5402	5402	5402	5402
Clip Rivet	BZ 9652	71557	9652	9652	9652	9652	9652	9652

(OVER)

1935 CAR
SERIAL NUMBERS

In order to clear up any misunderstanding which may exist, we offer a brief explanation of the car serial numbering system used for the 1935 Hudson and Terraplane models. This system is new, being inaugurated with the start of the 1935 season. By its use, it is possible by glancing at the serial number, to determine the year and model of the car.

STARTING SERIAL NUMBERS FOR 1935

Terraplane Special	51101	Hudson Special Eight	54101
Terraplane DeLuxe	52101	Hudson Deluxe Eight	55101
Hudson Six	53101	Hudson Custom Eight	56101

The first figure (5) which is the same for all models, denotes that the car is of 1935 production. The second figure identifies the chassis model. Thus, one (1) denotes Terraplane Special; two designates Terraplane Deluxe; three (3) Hudson Six, etc.

It will be seen therefore that for any particular model the first two figures remain the same throughout production of that model. The succeeding figures are the only ones which change, thus: 51101, 51102, 51103, etc. Now when the number 51999 is reached it might be assumed the next number would be 52000. This is not case, as the first two figures (51) are disregarded in the numerical sequence. Therefore the next number after 51999 is 511000. This explains the existence so early in production of numbers with six figures.

In this brief explanation we have used the Terraplane Special series as an example, but the same system applies to all models. The main point to remember is that the first two Figures in the serial number remain the same throughout the year.

- - - - -

P. E. Jones,
Supervisor,
Parts Specifications Division,
Service Department

HUDSON MOTOR CAR COMPANY

PARTS PRICES AND PARTS SPECIFICATIONS

1935 SERIES BULLETINS

No. 9

Date 3/27/35

Form 8103

Subject

TO ALL DEALERS:

In the event of breakage of vacuum clutch control cable on the Hudson and Terraplane, it is not necessary to replace the entire cylinder assembly. Replacement of the cable and piston rod assembly may be easily accomplished, and this part is supplied as a separate item.

We give below a review of the part numbers involved for 1933, 1934 and 1935 models.

CLUTCH VACUUM CONTROL PISTON ROD AND CABLE ASSEMBLY

<u>Part No.</u>	<u>Total Length</u>	<u>Models</u>
BZ 43010	19"	1933 Hudson E
BZ 43471	11¼"	1933 Terraplane K and KU
BZ 46940	13-3/32"	1933 Terraplane KT
BZ 43471	11¼"	1934 Terraplane K-KS-KU First Type to car Nos. - K and KS 406268, KU 27595
BZ 46941	10-7/16"	1934 Terraplane K-KS-KU Second type after car Nos. - K and KS 406268, KU 27595
BZ 43675	12-9/32"	1934 Hudson LT-LTS-LL First type to car Nos. - LT and LTS 966462, LL 255720
BZ 46942	11-11/32"	1934 Hudson, LT-LTS-LL Second type after car Nos. LT and LTS 966462, LL 255720
BZ 46941	10-7/16"	1935 Terraplane and Hudson Six
BZ 43675	12-9/32"	1935 Hudson Eight

VACUUM
CLUTCH
CONTROL
CABLES

CORRECTIONS

Please make the following corrections in the 1935 Chassis Parts Book:

Page 49 under "STEERING GEAR"

BZ 46040 Shaft Bushing

This part will not be supplied separately, and will only be supplied as a part of the Housing Assembly.

Page 51 under "DRAG LINK"

BZ 35629 Socket

The correct symbol is BZ 45629.

(OVER)

CORRECTIONS

Page 55 under "BONNET"
BZ 108048 Bonnet rear corner cover
The correct symbol is BO 108058.

Page 64 under "wiring"
BM 47667 COIL TO DISTRIBUTOR WIRE ASSEMBLY
The correct symbol is BM 47767

Page 67 under "GENERATOR AND CONTROL"
BM 40602 Generator pulley (For 41161 generator)
As the 41161 Generator (Hot type) was replaced by the new air cooled type, this pulley is not used in 1935 production and should be cancelled.

BM 44117 Generator pulley

This pulley will not be supplied by the Hudson Motor Car Company as it is part of the Generator Assembly and must be obtained from the Electric Auto Lite Corporation, Toledo, Ohio. Please cancel this number.

Page 68 under "SWITCHES"
BZ 45978 Headlight dimmer switch
The correct symbol is BZ 48620

Page 68 under "SWITCHES" R.H.D."
BZ 45352 Headlight dimmer, switch
The correct symbol is BZ 48621

P. E. Jones,

Supervisor,
Parts Specifications Division,
Service Department.

HUDSON MOTOR CAR COMPANY

PARTS PRICES AND PARTS SPECIFICATIONS

1935 SERIES BULLETINS

No. 10
 Date 4/3/35
 Subject

Form 8103

TO ALL DEALERS:

This is the first of a series of bulletins which will acquaint you with new parts numbers and changes in parts which have taken place since the start of 1935 production. Succeeding bulletins in this series will bear the same bulletin number and will be distinguished by letters, A, B, C, etc.

Corrections and additions in your 1935 Parts Book should be made in accordance with each bulletin as it appears. An excellent plan is to write down next to the part number in the book the bulletin number reference of the change affecting that part.

1935 PARTS
 BOOK
 REVISIONS

<u>Part No.</u>	<u>Description</u>	<u>BRAKE S</u>		<u>TERRAPLANE</u>		<u>HUDSON</u>	
		<u>Spec.</u>	<u>Del.</u>	<u>Spec.</u>	<u>Del.</u>	<u>Spec.</u>	<u>Del.</u>
BX 48246	BRAKE CAM AND RETURN SPRING ARM ASSEMBLY - R.H. Replaces BX 45433						2
BX 48247	BRAKE CAM AND RETURN SPRING ARM ASSEMBLY - L.H. Replaces BX 45434						2
<u>HAND BRAKE - UNDER DASH TYPE</u>							
BT 48230	Hand brake lever sector spacer-large Replaces one BT 47161 on sector bolt which is lowest or, nearest the dash. Effective with car Nos. 517896 - 524494 - 532097 - 542770 - 557327 - 56749	1	1	1	1	1	1
BT 48398	HAND BRAKE CABLE END SWIVEL ASSEMBLY Replaces BT 47317. Effective with car numbers listed above	1	1	1	1	1	1
BT 47317	HAND BRAKE CABLE END SWIVEL ASSEMBLY Again used - replacing BT 48398. Effec- tive with car Nos. 518634 - 524691 - 532232 - 542929 - 551397 - 56780	1	1	1	1	1	1
BT 48237	Brake lever pawl rod - replaces BT 47164	1	1	1	1	1	1
<u>DRAG LINK</u>							
C 47020	DRAG LINK ASSEMBLY	1	1				
C 47026	DRAG LINK AND PLUGS ASSEMBLY This drag link, formerly used on cars with side mount tire, is now used on all Terraplane, due to the use of the 32½" springs on these models. Effective with car Nos; 518051 - 525443	1	1				

(OVER)

No. 10

1935 PARTS BOOK
REVISIONS

<u>Part No.</u>	<u>Description</u>	<u>TERRAPLANE</u>		<u>HUDSON</u>		
		<u>Spec.</u>	<u>Del. 6</u>	<u>Spec.</u>	<u>Del.</u>	<u>Cust.</u>
F 47208	FRONT SPRING ASSEMBLY This spring, formerly used only on cars with side mount tire, is now used on all Terraplanes. Effective with car numbers 518051 - 525443. (See change In drag link).	2	2	8	8	8
BZ 47213	Front spring cover assembly - front Supersedes BZ 45600	2	2			
BZ 47214	Front spring cover assembly - rear Supersedes BZ 45601 Used on all Terraplanes, effective with car numbers listed above.	2	2			

P. E. Jones,

Supervisor,
Parts Specifications Division,
Service Department.

HUDSON MOTOR CAR COMPANY PARTS PRICES AND PARTS SPECIFICATIONS

No. 10-A
Date 6/7/35

1935 SERIES BULLETINS

Form 8103

Subject

TO ALL DEALERS:

Please make the following revisions to the 1935 Chassis Parts Book. Heading indicate the group in the book in which the superseded numbers appear

1935
PARTS BOOK
REVISIONS

Part No.	Description	TERRAPLANE		HUDSON			
		Spec.	Del.	Spec.	Del.	Cust.	
48150	<u>BATTERY</u> BATTERY ASSEMBLY (Supersedes 45097) Effective with car Nos. 518826-424772-532284. Serviced direct by National Battery Co. St. Paul, Minn.	1	1	6	8	8	8
<u>GENERATOR AND CONTROL</u>							
47979	Generator Charge Regulator This combined relay and charge control replaces 41146 Relay Assy. and 45102 Charge Control Assy. Effective with car Nos. 525480-532602-543383-551597-56961. Also used on Terra. Special when equipped with Radio, starting car No. 5111666. Serviced direct by Electric Auto-Lite Corp., Toledo, Ohio.	1	1	1	1	1	1
<u>DIFFERENTIAL AND CARRIER</u>							
BZ 71237	Differential carrier to housing bolt nut. Replaces BZ 62 for all car	8	8	8	8	8	8
BX 48343	Pinion oil seal (Replaces 44589) Effective with car Nos. 5118765-528661-534757-545034-552352-561380	1	1	1	1	1	1
<u>DRIVE SHAFT</u>							
BX 48341	DRIVE SIAAFT OIL SEAL ASSEMBLY Replaces 44566 Felt Washer Assembly; with car Nos. 5117404-528145-534233	2	2	2			
BX 71577	Drive shaft, nut (Replaces 71179)	2	2	2	2	2	2

(OVER)

No. 10-A

1935
PARTS BOOK
REVISIONS

REAR WHEEL BEARINGS

<u>Part No.</u>	<u>Description</u>	<u>TERRAPLANE</u>		<u>HUDSON</u>		
		<u>Spec.</u>	<u>Del.</u>	<u>Spec.</u>	<u>Del.</u>	<u>Cust.</u>
BX 48339	Wheel bearing adjusting cap oil seal Replaces 42615 Oil Seal, Starting car Nos. 4118655-528609-534689	2	2	2		

CLUTCH

BT 48687	SHIFTER YOKE SHAFT COUPLING LEVER ASSY. Replaces 43940	1	1	1	1	1	1
BT 48691	Shifter yoke shaft transmission lock operating lever (Low and reverse) Supercedes 47132. BT 71497 Screw and BM 272) nut are cancelled. These Changes effective with car Nos. 5122083- 529520-535415-562553-561455						
BT 45154	Engaging spring - inner Usage increased from 3 to 6 with Terraplane Engine No. 134059 and Hudson Six 75247	6	6	6			

CLUTCH ASSEMBLY

		1	1	1	1	1	1
BT 434188	SHIFTER YOKE SHAFT COUPLING LEVER ASSY. Replaces 47130. Effective with car Nos. 5122083- 529520-535415-545487-552553-561455.	1	1	1	1	1	1

P. E. Tones,
Supervisor,
Parts Specifications Division,
Service Department

HUDSON MOTOR CAR COMPANY

PARTS PRICES AND PARTS SPECIFICATIONS

1935 SERIES BULLETINS

No. 10-B

Date 6/14/35

Form 8103

Subject

TO ALL DEALERS:

Please make the following revisions to the 1935 Chassis Parts Book. Heading indicate the group in the book in which the superseded numbers appear

1935
PARTS BOOK
REVISIONS

HAND BRAKE - UNDER DASH TYPE

Part No.	Description	TERRAPLANE		HUDSON			
		Spec.	Del.	Spec.	Del.	Cust.	
		6	8	6	8	8	8
46619	Hand brake lever pivot bolt spring washer. This is a new part which entered Production March 12, 1935.	1	1	1	1	1	1

FRAME

BZ 47657	Rear Shock absorber bracket - R.H.	1	1	1	1	1	1
BZ 47558	Rear shock absorber bracket - L.H.	1	1	1	1	1	1
BZ 545	Rear shock absorber bracket rivet	6	6	6	6	6	6

These brackets formerly used on Terraplane Special WITH FENDER WELL, are now used on all Terraplane Special cars - starting car No. 518051 At the same time 47550 Bracket Assy. 46692 Reinforcement and 3197 Rivet were cancelled.

C 475-14	FRAME ASSEMBLY	1					
C 47516	FRAME ASSEMBLY		1				
C 47536	SIDE MEMBER ASSEMBLY - R.H.	1	1				
C 47537	SIDE MEMBER ASSEMBLY - L.H.	1	1				
BZ 47553	Front spring front bracket - R.H.	1	1				
BZ 47554	Front spring front bracket - L.H.	1	1				

Those parts formely used on Terraplane with fonder well, are now used on all Terra car No. 518051-525443.

THROTTLE CONTROL

Cancel 40682 Manifold bellcrank return spring anchor pin. This part cancelled from production effective with car Nos. 5112600-526249-543792-551821-561073.

(OVER)

1935
PARTS BOOK
REVISIONS

RADIATOR

Part No.	Description	TERRAPLANE		HUDSON			
		Spec.	Del.	Spec.	Del.	Cust.	
A 47068	Radiator Assembly } McCord		1				
A 47069	Radiator Assembly }			1			
A 47333	Radiator Assembly } Harrison		1				
A 47334	Radiator Assembly }			1			
C 45568	Core Assembly } McCord		1				
C 45569	Core Assembly }			1			
C 46670	Core Assembly } Harrison		1				
C 46672	Core Assembly }			1			
C 45579	Mounting strap } McCord		1				
C 45580	Mounting strap)			1			
C 46675	Mounting strap) Harrison		1				
C 46677	Mounting strap)			1			

Make corrections and additions as noted above.
The Harrison and McCord radiators were used optionally from first production.

COIL

45350	COIL - COMPLETE (Supersedes 45349) Effective with car No. 5114122 Serviced direct by Electric Auto-Lite Corp., Toledo, Ohio.	1					
-------	---	---	--	--	--	--	--

SWITCHES

BO 48243	LIGHTING SWITCH ASSY. (Replaces 47632 & 47466)	1	1	1	1	1	1
BO 4821-14	Lighting switch knob (Replaces 45741) In this rotary type switch the knob fastens to shaft with a set screw. BO 46563 Knob Retainer is discontinued. These changes effective on Terraplane Special with car No. 5117330. Other car numbers not available.	1	1	1	1	1	1
48620	Headlight dimmer switch (Replaces 45978) This is a change in part number only.	1	1	1	1	1	1

P. E. Jones,
Supervisor,
Parts Specifications Division,
Service Department

HUDSON MOTOR CAR COMPANY

PARTS PRICES AND PARTS SPECIFICATIONS

1935 SERIES BULLETINS

No. 10-C

Date 7/2/35

Form 8103

Subject

TO ALL DEALERS:

Please make the following revisions to the 1935 Chassis Parts Book. Heading indicate the group in the book in which the superseded numbers appear

1935
PARTS BOOK
REVISIONS

CARBURETOR AND FUEL PUMP

Part No.	Description		TERRAPLANE		Spec.		HUDSON		
			Spec.	Del.	6	8	Del.	Cust.	
47150	Carburetor air cleaner)		1						
45191	Carburetor air cleaner) Without Electric Hand		1		1	1	1		
47151	Carburetor air cleaner)			1					
48615	Carburetor air cleaner) With Electric Hand	*	1	1	1	1	1	1	
<p>The 186115 Standard Air Cleaner is used on all cars equipped with Electric Hand, except when Heavy Duty cleaner is specified. Effective with car Nos. 5112600-526249-532968-54792-551821-561073.</p>									
BM 48652	Carburetor air cleaner - Replaces 46819	*	1	1	1				
BM 48659	Carburetor Air Cleaner Cover Assembly	*	1	1	1				
BM 48653	Carburetor air cleaner - Replaces 46852	*				1	1	1	
BM 48654	Carburetor air cleaner brace - Replaces 46853	*				1	1	1	
<p>These Heavy Duty Air Cleaners are supplied through Service - also on Special Order in production</p>									
BM 48869	Carburetor air cleaner baffle (Supplied through Service for Heavy Duty Air Cleaners	*	1	1	1	1	1	1	
45191	Carburetor air cleaner (Without Elec. Hand) Replaces 47150 on Terraplane Special with Car No. 5119842	*	1	1		1	1	1	
BZ 70563	Carburetor choke wire bracket lock washer Internal tooth type lock washer assembled between choke wire bracket and carburetor		1						
BZ 48609	FUEL PUMP TO CARBURETOR PIPE ASSEMBLY Replaces 45477 with car Nos, 543792-551821-561073	*				1	1	1	

(OVER)

1935
PARTS BOOK
REVISIONS

CLUTCH VACUUM CONTROL

TERRAPLANE

HUDSON

<u>Part No.</u>	<u>Description</u>		<u>TERRAPLANE</u>		<u>HUDSON</u>			
			<u>Spec.</u>	<u>Del.</u>	<u>Spec.</u>	<u>Del.</u>	<u>Cust.</u>	
			<u>6</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>8</u>	
BZ 48895	Clutch vacuum control valve plug This is a thimble -type hole plug located in top of vacuum control and accelerator valve assembly.	*	1	1	1	1	1	1

SWITCHES - R.H.D.

48621	Headlight dimmer switch (Replaces 45352) A Part number change only	*	1	1	1	1	1	1
-------	---	---	---	---	---	---	---	---

WIRING

47575	BATTERY TO STARTER SWITCH CABLE ASSEMBLY (Replaces 45810) This is a part number change only.		1	1	1	1	1	1
-------	---	--	---	---	---	---	---	---

GENERATOR AND CONTROL

Cancel BM 40602 Generator pulley. This is not used
in 1935 production.

Cancel Bm 44117 Genefator pulley. This part must be
obtained from the Electric Auto-Lite Corp., Toledo,
Ohio.

P. E. Jones,

Supervisor,
Parts Specifications Division
Service Department

HUDSON MOTOR CAR COMPANY

PARTS PRICES AND PARTS SPECIFICATIONS

1935 SERIES BULLETINS

No. 10-E

Date 7/30/35

Subject

Form 8104A

TO ALL DEALERS:

Please make the following revisions to the 1935 Chassis Parts Book. Heading indicate the group in the book in which the superseded numbers appear

1935
PARTS BOOK
REVISIONS

EXHAUST MANIFOLD

<u>Part No.</u>	<u>Description</u>		<u>TERRAPLANE</u>		<u>HUDSON</u>		
			<u>Spec.</u>	<u>Del.</u>	<u>Spec.</u>	<u>Del.</u>	<u>Cust.</u>
			<u>6</u>	<u>8</u>	<u>6</u>	<u>8</u>	<u>8</u>
F 48582	Exhaust manifold gasket - end (Supersedes 38038)	*	2	2	2		
F 48583	Exhaust manifold gasket - center (Supersedes 38039)		1	1	1		
F 48584	Exhaust manifold gasket - end (Supersedes 53190)	*				2	2
F 48585	Exhaust manifold gasket - intermediate (Supersedes 33191)	*				2	2
F 48586	Exhaust manifold gasket - center (Supersedes 33192)	*				1	1

INTAKE MANIFOLD

BM 48590	Intake to exhaust manifold gasket Supercedes 40626	*	1	1	1		
F 48591	Intake to exhaust manifold gasket (Supersedes 42019)	*				1	1
F 48589	Intake manifold to cylinder gasket (Supersedes 38007)	*	1	1	1		
F 48587	Intake manifold to cylinder gasket (Supersedes 33171)	*				2	2
F 48588	Intake manifold to cylinder gasket (Superseds 33172)	*				2	2

The new gaskets are of steel - asbestos construction, and are about 1/64" thinner than the old gaskets. The new gaskets must not be used to replace the old except in sets. Car numbers at which the above change took place are not available.

SPRINGS - REAR

BZ 47288	Spring Clip plate - R.H.	1	1	1	1	1	1
BZ 47289	Spring Clip plate - L.H.	1	1	1	1	1	1

These plates, formerly used on Terraplane Special only when equipped with fender wells, are now used on all Terraplanes and Hudsons. Effective with car No. 518051

(OVER)

1935
PARTS BOOK
REVISIONS

BATTERY

<u>Part No.</u>	<u>Description</u>	<u>TERRAPLANE</u>		<u>HUDSON</u>			
		<u>Spec.</u>	<u>Del.</u>	<u>Spec.</u>	<u>Del.</u>	<u>Cust.</u>	<u>8</u>
48152	BATTERY ASSEMBLY (Supersedes 45099) * Effective with Car Nos. 546637-553063 Also used on Long Wheelbase Hudson Special and DeLuxe cars after Car Nos. 57734-5862.13. Serviced direct by Electric Battery Co, Philadelphia, Pa.				1	1	1

RADIO
ANTENNA AND LEAD-IN

HA 48569	ANTENNA COMPLETE	*	1	1	1	1	1	1
BO 48213	ANTENNA AND SUPPORT ASSEMBLY	*	1	1	1	1	1	1
BO 48224	Antenna spacer	*	2	2	2	2	2	2
BO 48226	Antenna spacer support - front	*	1	1	1	1	1	1
BO 48227	Antenna spacer support - rear	*	1	1	1	1	1	1
BO 48228	Antenna rubber cover - short	*	1	1	1	1	1	1
BO 48229	Antenna rubber cover - long	*	1	1	1	1	1	1
BO 91397	Antenna rubber cover cement				As required			
BO 44238	Antenna rubber tape				As required			

This is the second type running board antenna with rubber covering which became effective on radio equipped cars with Car Nos, 516865 - 523752 - 531820 - 542496 - 551169 - 56652. At the same time the following numbers were cancelled:

- 47423 ANTENNA AND LEAD-IN WIRE, COMPLETE
- 47473 ANTENNA AND SUPPORT ASSEMBLY - FRONT
- 47474 ANTENNA SPACER AND SUPPORT ASSEMBLY - REAR
- 47477 Antenna spacer grommet

RADIO - R.H.D

HA 48570	ANTENNA COMPLETE	1	1	1	1	1	1
BO 48219	ANTENNA AND SUPPORT ASSEMBLY	1	1	1	1	1	1

P. E. Jones

Supervisor,
Parts Specification Division
Service Department

HUDSON MOTOR CAR COMPANY

PARTS PRICES AND PARTS SPECIFICATIONS

1935 SERIES BULLETINS

No. 10-F

Date 7/30/35

Subject

Form 8104A

TO ALL DEALERS:

1935
PARTS BOOK
REVISIONS

FRONT SPRINGS

TERRAPLANE

HUDSON

Part No.	Description	Spec.	Del.	Spec.		Del.		Cust.
				6	8	8	8	
C 46850	Front spring leaf service kit (For 45280, 31" spring)	1	1	1				
C 48893	Front spring leaf service kit (For 47208, 32½" spring) *	1	1					
C 48894	Front spring leaf service kit (For 47209 spring) *					1	1	1

These kits available through service for adding an extra to front springs.
Cancel 46851 Spring leaf service kit.

FRAME

BZ 48592	Battery clamp bolt insulator Supersedes 44897	2	2	2	2	2	2
BM 71016	Battery clamp bolt (Supersedes 71231) This is a thinner insulator and longer bolt used with the higher batteries. Effective with car Nos. 5112636-526271-532977-543795-551824-561078	2	2	2	2	2	2

COIL

47194	COIL - COMPLETE (Supersedes 45350)	1					
BZ 47650	LOCK CYLINDER AND KEYS ASSEMBLY (Supersedes 109078)	1					
BO 9159	Bracket to dash bolt	2					

This is the same dash mounted coil as used on Terraplane DeLuxe and Hudson Six. Effective with car No. 51241893.
At the same time the following numbers were cancelled:

40606 Bracket
70139 Bracket to panel screw
70452 Bracket to panel screw washer
70676 Bracket to panel screw nut

(OVER)

1935
PARTS BOOK
REVISIONS

RADIO - MISCELLANEOUS

<u>Part No.</u>	<u>Description</u>	<u>TERRAPLANE</u>		<u>HUDSON</u>			
		<u>Spec.</u>	<u>Del.</u>	<u>Spec.</u>	<u>Del.</u>	<u>Cust.</u>	
	Cancel 45990 Capacitor (Generator)			6	8	8	8
	Cancel 70855 Capacitor (Generator) bolt						
	These parts discontinued in production with Car Nos. 515720 - 523385 - 531686 - 542309 - 551121 - 56603						

RADIO - CONTROL

BO 44142	Control flexible shaft clip	2	2	2	2	2	2
BO 18447	Control flexible shaft clip screw	1	1	1	1	1	1
BO 71075	Control flexible shaft clip screw nut	1	1	1	1	1	1
	This clip is used to attach flexible shafts to each other to reduce their Movement.						

RADIO - ANTENNA AND LEAD-IN

HA 48751	ANTENNA COMPLETE - Service Kit	*	1	1	1	1	1
BO 18447	Lead-in wire shielding loom Clip bolt		1	1	1	1	1
BO 71073	Lead-in wire shielding loom Clip bolt nut.		1	1	1	1	1
BM 71266	Lead-in wire terminal bolt (Replaces 18459)		1	1	1	1	1
BO 48757	Antenna insulator	*	8	8	8	8	8
BO 48758	Antenna clip	*	8	8	8	8	8
BO 48759	Antenna spring	*	4	4	4	4	4
BO 48760	Antenna anchor clip	*	4	4	4	4	4
BO 48765	Antenna choke	*	1	1	1	1	1

RADIO - R.H.D.

HA 48752	ANTENNA COMPLETE, Service Kit	*	1	1	1	1	1
	This is the new "Floor Type" Antenna which entered production with Car Nos. 5122893 - 5210165 - 555817 - 545722 - 552747 - 561527.						

P. E. Jones,

Supervisor,
Parts Specification Division
Service Department

**HUDSON MOTOR CAR COMPANY
PARTS PRICES AND PARTS SPECIFICATIONS
1935 SERIES BULLETINS**

Form 8103

No. 11

Date 4/4/35

Subject

TO ALL DEALERS:

The 1935 Numerical Parts Price List is off the press, and exceeds our expectations as to appearance and utility. A big volume of 328 pages filled from cover to cover with the information you have been waiting for - it contains some thirty thousand items with a description of each and the car on which it is used.

A tremendous amount of work has been necessary to compile and edit the material presented. It has involved checking each number, prefix and price, and we believe these to be more perfect in point, of accuracy than any information of a similar nature which we have previously published.

When you have seen your copy, which you will soon receive from your distributor, you will agree, we are sure, that it will become an indispensable part of stock room equipment and will be worth the price of ninety cents, which barely covers printing cost.

Extra copies may be secured at the regular price of ninety cents by ordering from your distributor.

P. E. Jones,

Supervisor,
Parts Specifications Division.

1935 NUMERICAL
PARTS
PRICE LIST

HUDSON MOTOR CAR COMPANY

PARTS PRICES AND PARTS SPECIFICATIONS

1935 SERIES BULLETINS

No. 12

Date 4/18/35

Form 8103

Subject

TO ALL DEALERS:

The following list prices on Service Parts are effective May 1, 1935.

<u>Part No.</u>	<u>Name</u>	<u>List Price</u>
29851	Frame End Assembly	3.15
30834	Rear Axle Carrier Assembly	50.00
30835	Rear Axle Carrier Assembly	50.00
31073	Front Wheel - Lacquer	6.00
31073	Front Wheel - Prime	5.00
3 1074	Rear Wheel - Lacquer	5.50
3 1074	Rear Wheel - Prime	4.50
31314	Rear Wheel - Lacquer	5.50
31314	Rear Wheel - Prime	4.50
33003	Rear Axle Carrier Assembly	50.00
33009	Rear Axle Carrier Assembly	50.00
34006	Rear Axle Carrier Assembly	50.00
35024	Piston ring	.50
35028	Piston ring	.50
36028	Carrier Assembly - Rear Axle	50.00
36029	Carrier Assembly - Rear Axle	50.00
36030	Carrier Assembly - Rear Axle	50.00
36031	Carrier Assembly - Rear Axle	50.00
36032	Carrier Assembly - Rear Axle	50.00
37042	Carrier Assembly - Rear Axle	50.00
37943	Carrier Assembly - Rear Axle	50.00
37737	Stop Light Switch	.50
37738	Stop Light Switch	.50
40339	Gasket - Cylinder Support Plate	.35
40662	Transmission Speedometer gear	2.50
40663	Transmission Speedometer gear	1.75
40737	Stop Light Switch	.50
40738	Stop Light Switch	.50
40980	Throttle Control Rod	.20
42145	Bushing - Pivot Pin	.25
42745	Spring Assembly - Front	4.00
42989	Pedal Lever Shaft Rod Lever	.05
43033	Brake Control Lever Bushing	.05
43167	Spring Assembly - Front	4.00
43170	Steering Spindle	4.00
43171	Steering Spindle	4.00
43443	Piston ring	.30
43455	Piston ring	.50
43447	Piston ring	.50
43452	Piston ring	.30
43454	Piston ring	.50

PARTS PRICE
CHANGES

(OVER)

No. 12PARTS PRICE
CHANGES

<u>Part No.</u>	<u>Name</u>	<u>List Price</u>
43456	Piston Ring	.60
44836	Frame Front Cross Member Assembly	7.50
44837	Frame Front Cross Member Assembly	10.00
44838	Frame Front Cross Member Assembly	8.00
44849	Frame Engine Support - R.H.	.50
44850	Frame Engine Support - L.H.	.50
45081	Stop Light Switch	.50
45082	Stop Light Switch	.50
45507	Shock Absorber Piston	.80
45513	Shock Absorber Piston Rod Guide	.60
45546	Horn Assembly	5.75
45547	Horn Assembly	5.75
45548	Horn Bracket Assembly	.50
45549	Horn Bracket Assembly	.50
45568	Radiator Core	27.50
45892	Wire Assembly Relay to Charge Control	.10
46026	Shock Absorber Value Plate	.30
46028	Shock Absorber Value Plate	.30
46378	Condenser	.24
46692	Shock Absorber Bracket Reinf.	.10
46774	Condenser	.48
46819	Air Cleaner	2.75
46948	Shock Absorber Head Grommet	.07
47375	Rear Brake Cable Mounting Bracket	.05
47467	Stop Light Switch	.50
47832	Hand Brake Lever Bolt Spacer	.10
48256	Diaphragm Rod Bellows	.60
60022	Camshaft	7.50
61515	Piston	1.50
61615	Gasket - Side Plate	.35
61615	Rear Axle Carrier Assembly	45.00
65026	Rear Axle Carrier Assembly	50.00
71522	Clevis Pin	.01
71525	Lift-the-Dot Stud	.05
71526	Bolt	.05
71535	Bolt	.02
71538	Screw	.03
71541	Screw	.01
71549	Screw	1.23
85731	Running Board Mldg. Side	1.25
100818	Roof Moulding R.H.	1.00
100819	Roof Moulding L.H.	1.00
102098	Dash Service Light	1.75
102531	Bumper Bar,	8.50
102740	Bumper Bar	8.50
107092	Wheelhouse Corner Plate Assembly R.H.	.30
107093	Wheelhouse Corner Plate Assembly L.H.	.30
111002	Bumper Bar	7.50
111006	Bumper Bar	8.50
111354	Locker Box Door	1.75
111471	Tire Cover Ring Assembly	3.25
111473	Tire Cover Drum Side Plate	4.25

(OVER)

HUDSON MOTOR CAR COMPANY PARTS PRICES AND PARTS SPECIFICATIONS

No. 12

Date 4/18/35

1935 SERIES BULLETINS

Form 8103

Subject

<u>Part No.</u>	<u>Name</u>	- 3 -	<u>List Price</u>
111516	Bumper Bar		7.50
111526	Bumper Bar		7.50
111531	Bumper Bar		7.50
111938	Body Cleaner Pint		.60
112464	Locker Box Door Assembly		2.75
112526	Radiator Underguard Assembly		.75
112839	Passenger Seat Back Frame Assembly		3.00
113833	Quarter Window Drain Trough Assembly R.H.		.85
113834	Quarter Window Drain Trough Assembly L.H.		.85
114777	Headlamp Lens		.90

PARTS PRICE
CHANGES

List prices on the following P.O.A. parts appear in the 1935 Numerical Parts Price List. These list prices should be deleted and the parts marked P.O.A. to indicate that special nets apply.

31000	Frame Assembly	P.O.A
31228	Transmission Assembly RHD 4-5/12 to 1	P.O.A
31229	Transmission Assembly RHD 4-5/12 to 1	P.O.A
31230	Transmission Assembly 4-1/13 to 1	P.O.A
31750	Frame Assembly 139"	P.O.A
31905	Radiator Assembly	P.O.A
33000	Front Axle Assembly	P.O.A
33001	Front Me Assembly RHD	P.O.A.
33023	Transmission Assembly 4-7/11 to 1	P.O.A
33031	Transmission Assembly 4-7/11 to 1	P.O.A
33260	Frame Assembly 119"	P.O.A.
33270	Frame Assembly 126"	P.O.A
33291	Cylinder and Piston Assembly	P.O.A
33300	Frame Assembly 119" RHD	P.O.A
33310	Frame Assembly 126" RHD	P.O.A
33404	Transmission Assembly 4-3/11 to 1 Overdrive	P.O.A
37141	Rear Axle 5-1/10 to 1	P.O.A
37200	Frame Assembly	P.O.A.
37201	Frame Assembly RHD	P.O.A.
37214	Cylinder and Piston Assembly	P.O.A.
37300	Frame Assembly 119"	P.O.A
37301	Frame Assembly 119" RHD	P.O.A.
37700	Cylinder and Piston Assembly	P.O.L.
37701.	Frame Assembly 126" RHD	P.O.A.
37781	Radiator Assembly	P.O.A.
37782	Radiator Assembly	P.O.A.
40331	Cylinder and Piston Assembly	P.O.A
40520	Radiator Assembly	P.O.A.
42011	Front Axle Assembly	P.O.A.
42012	Front Axle Assembly RHD	P.O.A.
42027	Cylinder and Piston Assembly	P.O.A.

(OVER)

P.O.A. PARTS
PRICES

<u>Part No.</u>	<u>Name</u>	<u>List Price</u>
41200	Rear Axle Assembly 4-1/9 to 1	P.O.A.
42941	Rear Axle Assembly 4-5/9 to 1	P.O.A.
42065	Radiator Assembly	P.O.A.
42133	Front Axle Assembly	P.O.A.
42134	Front Axle Assembly RHD	P.O.A.
42253	Rear Axle Assembly 4-1/9 to 1	P.O.A.
42350	Frame Assembly	P.O.A.
42351	Frame Assembly RHD	P.O.A.
42360	Frame Assembly	P.O.A.
42361	Frame Assembly RHD	P.O.A.
42370	Frame Assembly	P.O.A.
42371	Frame Assembly RHD	P.O.A.
42403	Cylinder Assembly	P.O.A.
42561	Radiator Assembly	P.O.A.
43310	Transmission Assembly	P.O.A.
43311	Transmission Assembly RHD	P.O.A.
43312	Transmission Assembly	P.O.A.
43313	Transmission Assembly RHD	P.O.A.
44500	Front Axle Assembly	P.O.A.
44501	Front Axle Assembly RHD	P.O.A.
44502	Front Axle Assembly	P.O.A.
44503	Front Axle Assembly	P.O.A.
44510	Front Axle Assembly	P.O.A.
44511	Front Axle Assembly RHD	P.O.A.
44530	Rear Axle Assembly 4-1/9 to 1	P.O.A.
44531	Rear Axle Assembly 4-1/9 to 1	P.O.A.
44532	Rear Axle Assembly 4-5/9 to 1	P.O.A.
44640	Rear Axle Assembly 4-5/9 to 1	P.O.A.
44719	Cylinder and Piston Assembly	P.O.A.
44720	Cylinder and Piston Assembly	P.O.A.
45155	Rear Axle Assembly 4-1/9 to 1	P.O.A.
45156	Rear Axle Assembly 4-5/9 to 1	P.O.A.
45326	Cylinder and Piston Assembly	P.O.A.
45780	Front Axle Assembly (Axleflex)	P.O.A.
45781	Front Axle Assembly (Axleflex) RHD	P.O.A.
45784	Front Axle Assembly (Axleflex)	P.O.A.
45785	Front Axle Assembly (Axleflex) RHD	P.O.A.
45788	Front Axle Assembly (Axleflex)	P.O.A.
45789	Front Axle Assembly (Axleflex) RHD	P.O.A.
47002	Rear Axle Assembly 5-6/10 to 1	P.O.A.
62307	Transmission Assembly 5-6/10 to 1	P.O.A.
63651	Frame Assembly	P.O.A.
64384	Radiator Assembly	P.O.A.
65071	Front Axle Assembly	P.O.A.
65104	Transmission Assembly 5-4/10 to 1	P.O.A.
65220	Frame Assembly	P.O.A.
65320	Frame Assembly RHD	P.O.A.

P. E. Jones
Supervisor
Parts Specifications Department
Service Department

HUDSON MOTOR CAR COMPANY
PARTS PRICES AND PARTS SPECIFICATIONS
1935 SERIES BULLETINS

Form 8103

No. 13

Date 5/1/35

Subject

TO ALL DEALERS:

Our Parts Department from time to time receives orders for painted parts on which the information given is insufficient for us to determine the color desired. This, of course, delays shipment until more detailed information is secured.

Color Code letters should not be used. These letters are for Sales Department only, and are misleading when employed for the purpose of specifying the color of service parts. The reason for this is that a color combination may be changed in production without a change in Code letters. Thus it is possible for a Code letter to represent one color during late 1934 and still another for 1935.

If the exact name of the desired color is not known, indicate the general color - such as brown, blue, green, - and give the serial number of the car for which the part is ordered, for example:

1 A 112090 Rear Fender - R.H.

Blue, for 1935 Hudson #56456

Your co-operation in this respect will greatly expedite handling of your orders and eliminate costly and unnecessary delays.

We list below the parts necessary to convert the folding type passenger seat used in the Terraplane Special Coach to the sliding type used in the Terraplane Deluxe Coach. This will satisfy the demand of those who desire to have the sliding seat in the Special Coach, without having to purchase a complete seat.

PARTS NEEDED TO INSTALL SLIDING TRACK ON TERRAPLANE
SPECIAL COACH RIGHT FRONT SEAT

PART NO.	NAME	LIST EACH
1 BO 108545	Track - outer	1.50
1 BO 108547	Track - inner	1.65
1 BO 71380	Clevis pin	.02
1 BO 71381	Clovis pin	.02
1 BO 71384	Bolt	.02
1 BO 71466	Bolt	.02
1 BO 108531	Link	.05

(Over)

ORDERING
PAINTED PARTS

<u>PART NO.</u>	<u>NAME</u>	<u>LIST PRICE</u>
4 BO 108530	Bracket	.05
2 BT 40456	Lockwasher	.03
8	1/4" x 1 1/4" Bolt	
8	1/4" Nut	
8	1/4" Lockwasher	

No drilling of holes is necessary, either in seat or floor boards. However, the cushion cover and spring must be removed from the seat base in order to attach the sliding rails. Also the carpet must be cut and bound to provide for the attachment of the rails to the floor. This entire operation requires about three hours labor.

On page 7 of the December 1933 Terraplane Chassis Parts Book, 42135 Axle Center Assembly is listed as being used on KU models. This is an error, as 4308 Axle Center was used from first production of the KU Series.

Please refer to page 27 of the November, 1934 Chassis Parts Book and delete the following items:

- BM 42078 Breather Tube Assembly
- BM 42087 Breather Tube support
- BM 33166 Breather Tube gasket
- EM 71250 Breather Tube bolt
- BM 35831 Breather Tube clip
- BO 18447 Breather Tube clip clasping bolt
- BO 12799 Breather Tube clip clamping bolt nut.

These parts are not used on 1934 Models

P. E. Jones,
 Supervisor,
 Parts Specifications Division
 Service Department

HUDSON MOTOR CAR COMPANY PARTS PRICES AND PARTS SPECIFICATIONS

No. 14

Date 5/27/35

1935 SERIES BULLETINS

Form 8103

Subject

TO ALL DEALERS:

SERVICE PARTS
PRICES

The following prices on Service Parts are effective immediately.

<u>PARTS NO.</u>	<u>DESCRIPTION</u>	<u>LIST PRICES</u>
1634	Transmission Control "Cross Shift" Diaphragm Housing Bolt	.01
1399	Transmission Control "Cross Shift" Diaphragm Housing Bolt Lock Washer	.30
6238	Bonnet Bumper to Retainer Rivet	.01
12438	Transmission Cover Expansion Plug	.01
32012	High Tension Wire Insulator	.03
40416	Drag Link Boat Lace	.01
43010	Cl. Vac. Control Piston Rod & Cable Assembly	1.45
43042	Acc. C/S Carb. Pull Rod Lever	.05
43043	Acc. C/S Clutch Vac. Control Lever	.05
43471	Cl. Vac. Control Piston Rod & Cable Assembly	1.45
44142	Radio Control Flexible Shaft Clip (Cad.)	.01
45157	Coil to Dist. Wire Term. Insulator (Coil End)	.05
45305	Rr. Spring Shackle Threaded Bush. Plug	.05
46017	Shock Absorber Piston - Frt. & Rr. Spicer #105-9-1	.35
46483	Propeller Shaft Assembly (without Noback)	24.50
46615	Rear Spring Rebound Clip (Bolted type)	.20
46616	Rear Spring Rebound Clip (Bolted type)	.20
46617	Rear Spring Rebound Clip (Band Eye type)	.20
46676	Radiator Mounting Strap	1.75
46679	Radiator Inlet	.75
46940	Cl. Vac. Control Cylinder Piston Rod Assembly	1.45
47062	Camshaft Gear	4.60
47333	Radiator Assembly (Inc. Shell) Harrison	60.00
47334	Radiator Assembly (Inc. Shell) Harrison	62.50
47352	Brake Pedal Push Rod Adj. End Tension Spring	.01
48077	Transmission Control Sel. Wire Conn. Assy. (Male half)	.60
48073	Transmission Cont, Sel. Wire Conn. Assy. (Female half)	1.00
480944	Piston Rod Guide Retainer Gasket	.05
48188	Frt. Shock Abs. Brkt. (Upper) Right	1.00
48189	Frt. Shock Abs. Brkt. (Upper) Left	1.00
48222	Radio Antenna Spacer & Support Assembly - Front	.07
48223	Radio Antenna Spacer & Support Assembly - Rear	.07
48232	Hand Brake Lever Bracket	.40
48237	Hand Brake Lever Pawl Rod	.15
48243	Lighting Switch Assembly	1.25
48244	Lighting Switch Knob	.20
48246	Brake Cam. & Return Spring Arm Assembly - R.	1.00
48247	Brake Cam. & Return Spring Arm Assembly - L.	1.00
48251	Power Unit Intake Cov. & Elbow Assembly	2.00
48262	Front Spring Leaf #3	1.05
48263	Front Spring Leaf #4	.85
48264	Front Spring Leaf #5	.65

(OVER)

<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>LIST PRICE</u>
48265	Front Spring Leaf #6	.50
48266	Front Spring Leaf #7	.35
48274	Front Spring Leaf #3	1.25
48275	Front Spring Leaf #4	.85
48276	Front Spring Leaf #1	1.50
48277	Front Spring Leaf #2	1.10
48278	Front Spring Leaf #3	1.25
48279	Front Spring Leaf #4	.85
48280	Front Spring Leaf #5	.75
48281	Front Spring Leaf #6	.50
48282	Front Spring Leaf #7	.55
48283	Front Spring Leaf #9	.30
46284	Rear Spring Leaf #7	.75
48285	Rear Spring Leaf #8	.50
48286	Rear Spring Leaf #9	.50
48287	Rear Spring Leaf #4	.30
48288	Boar Spring Leaf #2	1.75
48289	Rear Spring Leaf #3	1.65
48290	Rear Spring Leaf #4	1.25
48291	Rear Spring Leaf #5	1.15
48316	Front Spring Center Bolt	.20
48317	Rear Spring Center Bolt	.20
48118	Rear Spring Center Bolt	.20
48619	Front Spring Rebound Clip (bolted type)	.15
48320	Rear Spring Clip	.15
48521	Rear Spring Clip	.15
48322	Rear Spring Clip	.20
48323	Rear Spring Clip	.20
48524	Rear Spring Clip	.20
48327	Brake Shoe Lining Mortar	.25
48349	Radio Antenna Rubber Cover End Plug	.01
48393	Electric Hand Power Unit Intake Hose - Long	.70
48394	Electric Hand Power Unit Intake Hose Strap	
48397	Radio Antenna Lead-In Rubber Cover	.02
48405	Electric Hand Power Cyl. Mtg. Stud Reinf. Washer	
48406	Electric Hand Power Cyl. Mtg. Bracket Assembly	.,U
48409	Electric Hand Power Cyl. End Plate Assembly	1.15
48411	Electric Hand Power Cyl. End Plate Piston Seal	1 C1,
48412	Electric Hand. Power Cyl. End Plate Piston Seal Look	1c)
48415	Electric Hand Power Cyl. End Plate Gasket	.05
48416	Electric Hard Power Cyl. Piston Assembly	4.00
48427	Electric Hand Power Cyl. Piston Rod End	P, 5
46,128	Electric Hand Power Cyl. End Plate Stay Bolt	10
48429	Electric Hand Power Cyl, Flared Tube Elbow	.25
48430	Electric Hand Diaphragm Cyl. Comp.	3.40
48433	Electric Hand Diaphragm	.15
48434	Electric Hand Diaphragm Plate	.10
43435	Electric Hand Diaphragm Flanged Plate	.75 73
48436	Electric Hand Diaphragm Washer	.01
48457	Electric Hand Diaphragm Rod	G5
48458	Electric Hand Diaphragm Rod Guard Retainer	.25
48442	Electric Hand Diaphragm Housing Washer	.02

SERVICE PARTS
PRICES

<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>LIST PRICE</u>
40443	Electric Hand Diaphragm Housing Bolt	.10
48444	Electric Hand Diaphragm Return Spring	.30
4845	Electric Hand Diaphragm Cyl. Mtg. Plug	.02
48446	Electric Hand Diaphragm Cyl. Mtg. Plug Gasket	.02
48450	Electric Hand Selector Valve to Bracket Gasket	.20
48451	Electric Hand Selector Valve Flange Elbow (Air Hose)	.45
48452	Electric Hand Selector Valve Flange Elbow Gasket	.02
48456	Electric Hand Selector Valve Body Expansion Plug	.05
48460	Electric Hand Selector Valve Stop Plate	.65
48461	Electric Hand Selector Valve Stop Plate	.05
48462	Electric Hand Selector Valve Air Cleaner Mtg. Bracket	.35
48463	Electric Hand Selector Valve to Cyl. Tube Assy. (Stud End)	.35
48466	Electric Hand Selector Valve to Cyl. Tube Elbow	.30
48467	Electric Hand Selector Valve to Cyl. Tube Assy.(Piston Rod End)	.35
48475	Electric Hand Selector Valve Solenoid Wire Terminal	.02
48476	Electric Hand Selector Valve Solenoid Wire Loom	.02
48487	Electric hand Selector Switch Hsg. Strg. Column Cap	2.20
48488	Electric Hand Selector Housing End Cap	1.30
48492	Electric Hand Selector Switch Shaft and Lever Assembly	3.20
48494	Electric Hand Selector Switch Shaft and Bushing Assembly	.50
48496	Electric Hand Selector Switch Shaft Pin	.01
48497	Electric Hand Selector Switch Shaft Return Spring	.04
48498	Electric Hand Selector Switch Shaft' & Lever Coupling	.30
48505	Electric Hand Selector Lever Assembly	2.00
48509	Electric Hand Selector Lever Spring	.03
48510	Electric Hand Selector Lever Spring Stop Washer	.01
48518	Electric Hand Selector Switch Base Lock Ring	.02
48519	Electric Hand Selector Switch Rotor Assembly	.40
48523	Electric Hand Selector Switch Rotor Returning Spring	.05
48524	Electric Hand Selector Cut-Out Switch	.25
48525	Electric Hand Selector Cut-Out Switch Cover Plate	.01
48526	Electric Hand Selector Cut-Out Switch Dover Plate Screw	.05
48532	Electric Hand Main Contact Shift Block Assembly	.60
43539	Electric Hand Main Contact Plate Cover Insulator	.10
48511	Electric Hand Selector Valve Chock Valve	.04
48542	Electric Hand Selector Valve Check Valve Nut	.35
48559	Electric Hand Power Unit Ground Wire Assembly	.20
48561	Electric Hand Main Contact Switch Shift Lever & Pin Assy.	.45
48564	Electric hand Main Contact Switch Shift Lever Pin Bushing	.05
43567	Trans. Cover Assembly	5.00
48568	Electric Hand Switches and Wires Assembly	5.00
48590	Intake Manifold to Exh. Manifold Gasket	.05
48594	Steering Wheel (Black)	4.00
48595	Steering Wheel (Black)	4.25
46596	Steering Wheel (Gray)	6.50
48597	Steering Wheel (Tan)	6.50
48600	Electric hand Power Unit Intake Hose	.45
48601	Electric Hand Power Unit intake Pipe (Long)	.65
48602	Electric Hand Power Unit intake Pipe (Long)	.65

(OVER)

<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>LIST PRICE</u>
48603	Electric Hand Power Unit Intake Pipe (Long) Clip	.03
48604	Electric Hand Power Unit Intake Pipe Assembly (Short)	.30
48606	Electric Hand Power Unit Vac. Pipe (Short) Assembly	.35
48608	Electric Hand Power Unit Vac. & Intake Hose Clip (Double)	.01
48609	Fuel Pump to Carb. Pipe Assembly	.35
48613	Intake Manifold Stud	.05
48614	Electric Hand Power Unit Intake Pipe (Short) Union	.25
48616	Electric Hand Power Unit Intake Hose	.50
48619	Hand Brake Lever Pivot Bolt Spring Washer	.02
48620	Dimmer Switch	1.00
48643	Front Spring Leaf #3	1.00
48644	Front Spring Leaf #4	.85
48645	Front Spring Leaf #5	.65
48648	Rear Shock Absorber Assembly	5.50
48649	Rear Shock Absorber Assembly	5.50
48700	Electric Hand Power Unit Complete	19.00
48701	Electric Hand "Cross Shift" Switch Assembly	1.50
48702	Electric Hand "Cross Shift" Switch Rod Tapped Sleeve	.10
48705	Electric Hand Grease (1-oz. contained)	.05
70934	Tubular Rivet	.01
71376	Trunk Hinge Bolt Plain Washer	.01
71464	Tire Cover Anti-Rattler Rivet	.01
71480	Diff. Carrier Brg, Cap Screw	.05
71494	Window Glass Run Sheet Metal Screw	.03
71515	Window Glass Run Sheet Metal Screw	.01
71557	Frnt. Spring Rebound Clip Rivet	.05
71558	Slot Hex Head Screw	.05
71559	Hot Water Heater Door Screw	.05
71560	Hot Water Heater Door Screw Washer	.05
71561	Radio Antenna Spacer Clip Drive Screw	.50
71568	Electric Hand Selector Hsg. End Cap Bolt	.15
71569	Electric Hand Selector Valve to Bracket Bolt	.01
71571	Elec. Hand Selector Valve Solenoid Wire Junction Block Bolt	.01
71572	Electric Hand Selector Switch Hst. Strg. Column Cap Screw	.15
71573	Switch Hsg. Strg. Column Cap Screw	.15
71576	Folding Top Frt. Header Rail Weatherstrip Ret. Screw	.01
71579	Body Bolt #10	.10
71580	Body Bolt #15	.10
71681	Dust Boot to Comp. Bottom Fastener Stud.	.05
71582	Rear Compt. Floor Board to Seat Tray Bolt	.01
71585	Tire Cover Drum Side Plate Hub Cap Spring Clip Rivet	.01
102752	Tail Lamp Housing Assembly	1.25
107510	Bonnet Side Hinge Rod	.10
107524	Bonnet Side Hinge Rod	.10
108358	Frnt. Dr. Wdo. Fin. Mldg. Trimboard	.08
108359	Qtr. Window Trimboard	.12
108360	Frnt. Dr. Wdo. Fin. Mldg. Trimboard	.08
108361	Frnt. Dr. Wdo. Fin. Mldg. Trimboard	.12
108662	Frnt. Dr. Wdo. Trimboard	.05
108363	Frnt. Dr. Wdo. Fin. Mldg. Trimboard	.10
108364	Br. Dr. Wdo. Fin. Mldg. Trimboard	.10
108365	Rr. Dr. Wdo. Fin. Mldg. Trimboard	.10
108371	Qtr. Wdo. Rear Side Member	.20
108432	Qtr. Wdo. Guide Assembly - Less Paint	.30
108199	Frnt. Dr. Panel Strainer Assembly	.26

<u>PART No.</u>	<u>DESCRIPTION</u>	<u>LIST PRICE</u>
108833	Quater Window Frame	.10
111152	Headlamp Housing Assembly (Black)	3.50
111186	Windshield Cleaner Tube (tubing to cleaner)	.05
111187	Windshield Cleaner Tube (tubing to manifold)	.20
111384	Tire Cover Ring Assembly - Lacquer	3.50
111384	Tire Cover Ring Assembly - Prime	3.00
111475	Tire Cover Ring Assy. (Rear Mount) (Colors only) - Lacquer	3.75
111475	Tire Cover Ring Assy. (Rear Mount) - Prime	3.00
111476	Ti ro Cover Ring Assy. (Rear Mount) (Colors only) - Lacquer	3.75
111476	Tire Cover Ring Assy. (Rear Mount) - Prime	3.00
111942	Carb. Choke - Wire and Knob Assembly	.40
111843	Carb. Choke - Wire and Knob Assembly	.40
111944	Luggage Carrier Fin. Mldg. Short	.60
112006	Bonnet Top & Side Panel Assembly - R. - Prime	12.50
112006	Bonnet Top & Side Panel Assembly - R. - Lacquer	15.00
112007	Bonnet Top & Side Panel Assembly - L. - Prime	12.50
112607	Bonnet Top & Side Panel Assembly - L. - Lacquer	15.00
112047	Bonnet Top & Side Panel Assembly - R. - Prime	10.00
112047	Bonnet Top & Side Panel Assembly - R. - Lacquer	12.50
112048	Bonnet Top & Side Panel Assembly - L. - Prime	10.00
112048	Bonnet Top & Side Panel Assembly - R. - Lacquer	12.50
112354	Windshield Assembly (Less Glass)	7.50
112426	Rear Door Wdo. Fin. Mdlg. Assy. - R	3.50
112427	Rear Door Wdo. Mldg. Assembly - L	3.50
112443	Rear Wdo. Fin. Mldg. - Inner	3.00
112457	Qtr. Wdo. Drain Trough Assembly - R.	.15
112458	Qtr. Wdo. Drain Trough Assembly - L.	.15
112462	Locker Box Door (Mahogany)	1.75
112474	Running Board Panel Assembly - R. (Less Mat) - Lacquer	6.00
112474	Running Board Panel Assembly - R. (Less Mat) - Prime	4.00
112475	Running Board Panel Assembly - L. (Less Mat) - Lacquer	6.00
112475	Running Board Panel Assembly - L. (Less Mat) - Prime or Enamel	4.00
112478	Running Board Panel Assembly - R. (Less Mat) - Lacquer	8.50
112478	Running Board Panel Assembly - R. (Less Mat) - Prime	6.50
112479	Running Board Panel Assembly - L. (Less Mat) - Lacquer	8.50
112479	Running Board Panel Assembly - L. (Less Mat) - Prime	6.50
112605	Dome Lamp Assembly	1.50
112614	W/S Header to Roof Panel Brace - Center	.15
112653	Roof Roar Corner Gusset	.10
112654	Folding Top Side Arm Assembly - R	4.50
112655	Folding Top Side Arm Assembly - L	4.50
112656	Folding Top Pillar and Hinge Assembly - R	4.50
112657	Folding Top Pillar and Hinge Assembly - L	2.00
112658	Top Frt. Header Trim Rail W/Strip Retainer	.15
1126159	Top Frt. Header Rail Bumper	.05
112660	Top Bow #1 to Folding Pillar Bolt	.06
112661	Top Box #1 to Folding Pillar Bolt Spacer	.05
112685	Front Door Window Glass Run Assembly	.75
122687	Rear Door Window Glass Run Assembly	1.00
112689	Door Wdo. Glass Run Assembly	.95

(OVER)

<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>LIST PRICE</u>
112714	Quarter Window Frame to Wheelhouse Bracket	.10
112748	Front. Door Lock Pillar Glass Channel & Bracket Comp. - R.	1.00
112749	Front. Door Lock Pillar Glass Channel & Bracket Comp. - L.	1.00
112752	Front. Door Window Regulator Assembly - R.	2.00
112753	Front. Door Window Regulator Assembly - L.	2.00
112761	Front. Door Trimboard Support (Enamel)	10
112762	Front . Door Hinge Pillar Glass Run & Channel Assembly - R.	.20
112763	Front . Door Hinge Pillar Glass Run & Channel Assembly - L.	.20
111273	Rad . Grill Assembly (Black Enamel)	5.00
112785	Rear Floor Mat - LHD	5.00
112786	Rear Seat Tray Floor Mat	4.00
112788	Rear License Plate Bracket Assembly (Enamel)	.40
112790	Front Door Belt Cross Member to Regulator Strap	.05
112794	Front Door Window Regulator to Pillar Strap Assembly - R.	.25
112795	Front Door Window Regulator to Pillar Strap Assembly - L.	.25
112798	Rear Floor Mat - RHD	5.00
112812	Front Door Window Regulator to Pillar Strap Assembly - R	.20
112813	Front Door Window Regulator to Pillar Strap Assembly -	.20
112836	W/S Header to Front End Panel Bracket Assembly - R	.10
112837	W/S Header to Front End Panel Bracket Assembly - L	.10
112892	Body Heater Assembly - R.	.75
112893	Body Header Assembly - L.	.75
112894	Body Header Assembly - R.	.75
112895	Body Header Assembly - L.	.75
112896	Body Header Assembly - R.	1.60
112897	Body Heater Assembly - L.	1.50
112898	Body Heater Assembly - R.	1.75
112899	Body Heater Assembly - L.	1.75
112935	Dash Hole Cover Plate	.05
112956	Roof Rear Corner Gusset Assembly	.05
113521	Front Door Bottom Weatherstrip & Cardboard Assembly	.30
113548	Upholstery Button	.02
113554	Assist Strap Assembly	1.75
113556	Assist Strap Assembly (Blue)	1.25
113557	Assist Strap Assembly (Blue)	1.25
113558	Assist Strap Assembly (Brown)	1.25
113560	Assist Strap Assembly (Green)	1.25
113561	Assist Strap Assembly (Green)	1.25
113696	Cowl Side Trim Panel (Black)	.20
113697	Cowl Side Trim Panel (Black)	.20
113723	Rear Window Trimboard Assembly - Lower	.60
113794	Rear Floor Carpet Assembly	7.50
113989-90	Body Header Trim Panel Assembly R. & L.	1.25
114000	Instrument. Cluster Comp. (Miles)	21.00
114001	Instrument. Cluster Comp. (Metric)	21.00
114002	Instrument. Cluster Comp. (Miles)	21.00
114003	Instrument. Cluster Comp. (Metric)	21.00
114004	Instrument. Cluster Comp. (Miles)	21.00
114005	Instrument. Cluster Comp. (Metric)	21.00
114121	Tire Cover Drum Side Plate Assembly - L. (Prime or Color) - Lacquer	4.75
114121	Tire Cover Drum Side Plate Assembly - Prime	3.50
1141212	Tire Cover Drum Side Plate Assembly - Lacquer	4.75
114122	Tire Cover rum Side Plate Assembly - Prime	3.50

**HUDSON MOTOR CAR COMPANY
PARTS PRICES AND PARTS SPECIFICATIONS
1935 SERIES BULLETINS**

Form 8103

No. 15

Date 6/7/35

Subject

TO ALL DEALERS:

A new Confidential Net Price List - No. 13 is now ready and will be mailed immediately. This supersedes all previous lists, which should be destroyed.

This new Net Price List is slightly different in form from previous issues, the items being arranged in groups similar to the Chassis Parts Book. Within each group items are listed numerically, and interchangeability of models is indicated.

We call your attention :especially to the companion booklet (Pink) designated **SELECTED PARTS PRICE LIST**, in which only list prices are shown. Those may be distributed to independent garages and dealers in your neighborhood and should be marked with the discount which you allow. We believe that used in this manner, they will assist you to secure a greater share of parts business from these sources.

A copy of this booklet is being included in your mailing. Extra copies are available and will be furnished upon request.

Your copy of the 1935 Body Parts Book has been mailed and we trust you will receive it in good condition. Your comments as to its form, arrangement, etc, will be welcome, and we solicit your aid in bringing to our attention any errors which you may discover.

P. E. Jones,
Supervisor,
Parts Specification Division
Service Department

CONFIDENTIAL
NET

BODY PARTS
BOOK

HUDSON MOTOR CAR COMPANY

PARTS PRICES AND PARTS SPECIFICATIONS

1935 SERIES BULLETINS

No. 16

Date 6/10/35

Form 8103

Subject

TO ALL DEALERS:

The following prices on Service Parts are effective immediately. Changes in list prices shown on Confidential Net Price List No. 13 are included in this list.

SERVICE PARTS
PRICES

<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>LIST PRICE</u>
1491	Pipe Plug	.10
2490	Bolt	.05
7525	Horn Bracket Nut	.05
10858	Tie Rod Yoke Pin	.50
19322	Rear Axle Cover Gasket	.25
22702	Piston Pin	.45
22703	Connecting Rod Bushing	.30
22779	Clutch Cover Gasket	.25
22788	Clutch Spring	.06
23291	Exhaust Manifold Gasket	.10
23622	Front Cover Gasket	.45
25306	Exhaust Manifold Gasket	.35
25308	Intake Manifold Gasket	.30
25617	Brake Support	.25
25618	Brake Support	.25
25836	Spring Leaf No. 1	2.25
25846	Spring Leaf No. 1.	3.10
25886	Spindle Pivot Pin	1.00
28068	Stop Lamp Switch	.50
28357	Manifold Gasket	.35
28956	Pivot Pin Bushing - Lower	.20
28957	Pivot Pin Bushing - Upper	.20
29321	Exhaust Manifold	5.00
29361	Clutch Cover Gasket	.25
29500	Front Spring Assembly	6.50
29836	Battery Cable	2.25
29896	Starting Crank Jaw	.85
29904	Inlet Valve	.50
29909	Exhaust Manifold Gasket	.20
29910	Exhaust Manifold Gasket	.12
29936	Intake Manifold Gasket	.12
30184	Rear Spring Assembly	7.50
30353	Gasoline Tank Cap	.35
30406	Lens Spring	.05
30573	Connecting Rod Bushing	.30
30868	Brake Spring Clip	per C .20
31001	Exhaust Pipe	1.76
31070	Intake Manifold Gasket	.12
31133	Clutch Cover Gasket	.25
31234	Pivot Pin	1.00
31877	Pivot Pin	1.00

(OVER)

SERVICE PARTS
PRICES

- 2 -

<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>LIST PRICE</u>
32128	Rear Spring Assembly	10.00
33148	Piston - Finished	2.60
33148	Piston - Semi-Finished	2.30
33332	Connecting Rod Bushing	.20
35009	Piston Pin	.40
35024	Piston Ring	.50
35026	Piston Ring	.50
36482	Muffler Assembly	.50
36505	Exhaust Manifold Gasket	4.00
37029	Piston Pin	.50
37776	Oil Check Valve Pin Assembly	.60
37862	Hub Cap	1.15
38372	Battery Cable Assembly	1.00
38751	Brake Lining & Rivets	5.15
38978	Ignition Wires (Boxed)	2.70
39264	Ignition Wires (Boxed)	1.80
40150	Front Cover Gasket	.25
40260	Fan Belt	1.10
40339	Cylinder Support Plate Gasket	.35
40737	Stop Lamp Switch Assembly	.50
40980	Throttle Control Rod	.20
42145	Pivot Pin Bushing	.25
42200	Frame Assembly	30.00
42295	Tail Pipe Assembly	1.50
42745	Front Spring Assembly	4.00
42747	Rear Spring Assembly	5.75
43167	Front Spring Assembly	4.00
43356	Battery Cable Assembly	1.65
43443	Piston Ring	.30
43445	Piston Ring	.50
43447	Piston Ring	.30
43452	Piston Ring	.50
43454	Piston Ring	.50
43456	Piston Ring	.50
43538	Ignition Wires (Boxed)	2.70
44069	Valve Spring	.25
45586	Valve, Spring	.25
45810	Battery Cable Assembly	1.00
46439	Ignition Wires (Boxed)	1.70
48132	Brake Lining & Rivets	5.20
48245	Brake Lining & Rivets	6.00
48582	Exhaust Manifold Gasket	.15
48583	Exhaust Manifold Gasket	.15
48584	Exhaust Manifold Gasket	.15
48585	Exhaust Manifold Gasket	.15
48586	Exhaust Manifold Gasket	.15
48587	Intake Manifold Gasket	.10
48588	Intake Manifold Gasket	.15

(OVER)

SERVICE PARTS
PRICES

PART NO.	DESCRIPTION	LIST PRICE
48589	Exhaust Manifold Gasket	.20
48591	Exhaust to Intake Manifold Gasket	.15
60027	Front Cover Gasket	.40
60315	Clutch Cover Gasket	.20
60463	Front Spring Assembly	4.55
60464	Rear Spring Assembly	5.00
60511	Pivot Pin Bushing	.10
60518	Tie Rod Yoke Bushing	.10
61034	Clutch Driving Disc.	1.00
61360	Valve Guide	.25
61491	Pivot Pin Bushing	.10
61615	Side Plate Gasket	.35
62078	Support Plate Gasket	.40
62079	Oil Deflector Gasket	.40
62103	Piston Ring	.35
62365	Rear Spring Assembly	5.00
62492	Battery Cable Assembly	1.00
62554	Front Plate Gasket	.40
63534	Piston Ring	.25
64311	Rear Spring Assembly	5.00
65018	Clutch Cover Gasket	.20
65304	Connecting Rod - R.H.	5.50
65305	Connecting Rod - L.H.	3.50
70085	Trans. Mainshaft Bearing	3.00
70901	Bolt	per C .40
81248	Rear Fender - R.H. - Prime	7.50
81248	Rear Fender - R.H. - Lacquer	7.50
81249	Rear Fender - R.H. - Prime	9.50
81249	Rear Fender - L.H. - Lacquer	7.50
85932	Door Handle & Cylinder Assembly	2.90
109323	Spare Tire Lock Assembly	.75
109324	Spare Tire Lock Assembly	1.25
111002	Front Bumper Outside Bar	7.50
114186	Trunk Lock Complete - R.H.	3.25
114187	Trunk Lock Complete - L.H.	3.25
114226	Trunk Panel Assembly - Lacquer	2230
114228	Trunk Panel Assembly - Prime	17.50
114234	Bonnet Side Hinge Rod	.15
114235	Bonnet Side Hinge Rod	.15
114242	Roof Panel - Prime	8.00
114246	Body Header Side Trim Rail Assembly - R.H.	.50
114247	Body Header Side Trim Rail Assembly - L.H.	.50
114269	Windshield Complete - Less Glass	7.50
114285	Rear Seat Tray Tire Well Assembly	2.50
114296	Rear Fender Assembly - R.H. - Prime or Enamel	9.00
114296	Rear Fender Assembly - R.H. - Lacquer	11.00
114297	Rear Fender Assembly - L.H. - Prime or Enamel	9.00

(OVER)

SERVICE PARTS
PRICES

<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>LIST PRICE</u>
114297	Rear Fender Assembly - L.H.	11.00
114416	Rear Window Finish Molding - Inner (Eucalyptus)	3.00
114424	Front Seat Back Valance	2.50
114435	Locker Box Door	1.75
114440	Tire Cover Ring Assembly - Lacquer	3.75
114440	Tire Cover Ring Assembly - Prime	3.00
114450	Instrument Panel - Eucalyptus)	8.50
114455	Instrument Mounting Pad	2.00
114490	Instrument Mounting Panel - LHD	2.25
114491	Instrument Mounting Panel - RHD	2.25
114492	Instrument Mounting Panel - RHD	2.25
114493	Instrument Mounting Radio Opening Cover	2.25
114547	Trunk Check Arm Lock Plate	.35
114590	Rear Door Handle Less Cylinder	1.50
114608	Trunk Lock Key	.25
114618	Tail Lamp & License Plate Bracket Clamp	.40
114631	Roof Molding	.85
114670	Gas Tank Gauge Cutout Cover Trimboard Assembly	.10
114673	Trunk Floor Tool Compartment Lid Trimboard Assembly	.60
114675	Trunk Floor Trimboard Assembly (Side Tire Mount)	1.50
114687	Trunk Floor Trimboard Assembly (Side Tire Mount)	1.25
114696	Trunk Floor Trimboard Assembly	1.50
114697	Locker Box Door Assembly	2.75
114726	Instrument Mounting Panel	1.10
114732	Finish Molding Assembly - R.H. (Peroba)	4.00
114733	Finish Molding Assembly - L.H. (Peroba)	4.00
114736	Finish Molding Assembly - R.H. (Peroba)	3.75
114737	Finish Molding Assembly - L.H. (Peroba)	3.75
114738	Finish Molding Valance - R.H. (Peroba)	1.20
114739	Finish Molding Assembly - L.H. (Peroba)	1.20
114740	W/S Finish Molding Assembly - R.H. (Peroba)	2.25
114741	W/S Finish Molding Assembly - L.H. (Peroba)	2.25
114742	Rear Window Finish Molding Inner (Peroba)	1.25
114743	Rear Window Finish Molding Valance (Peroba)	1.50
114744	Front Door Trim Panel Bead Molding - RH (Peroba)	1.20
114745	Front Door Trim Panel Bead Molding - LH (Peroba)	1.20
114746	W/S Finish Molding Joint Cover (Peroba)	.50
114747	Rear Door Trim Panel Bead Molding (Peroba)	1.00
114748	Front Seat Back Valance (Peroba)	2.50
114753	Rear Seat Tray Crossmember Shim	.05
114754	Rear Window Weatherseal	.25
114755	Instrument Mounting Panel - LHD (Peroba)	2.25
114756	Instrument Mounting Panel - RHD	2.25
114757	Locker Box Door	1.75
114761	Trunk Attaching Bolt Nut Retainer	.05
114762	Rear Seat Back Spring	3.75

P. E. Jones
Supervisor,
Parts Specification Division
Service Department

HUDSON MOTOR CAR COMPANY

PARTS PRICES AND PARTS SPECIFICATIONS

1935 SERIES BULLETINS

No. 17
 Date 6/17/35
 Subject

Form 8103

TO ALL DEALERS:

On all Orders for 1935 Hubs or Brake Service will supply the Hub and Brake Drum Assemblies.

This is necessary on account of the fact that the drum is machined after being rivet to the hub. Due to the clearance between drum and Hlub flange it is not practical to machine the drum separately and expect the Service Stations to maintain concentricity when assembling a new drum -to an old hub or vice versa. The following part numbers are affected;

- | | | |
|-------|-----------------|--|
| 47438 | Front Hub | - Use 47429 for Terraplane
- Use 47430 for Hudson (Except Custom 8) |
| 44972 | Front Hub | - Use 45009 for Hudson Custom 8 |
| 47443 | Front Drum | - Use 47429 for Terraplane |
| 47444 | Front Drum | - Use 47430 f or Hudson (Except Custom 8) |
| 37880 | Front Drum | - Use 45009 for Hudson Custom 8 |
| 47439 | Rear Hub | - Use 47431 for Terraplane
- Use 47432 for Hudson Six |
| 47440 | Rear Hub | - Use 47444 for Hudson Special & Deluxe 8 |
| 44975 | Rear Hub | - Use 45225 for Hudson Custom 8 |
| 47441 | Rear Drum Assy. | - Use 47431 for Terraplane |
| 47442 | Rear Drum Assy. | - Use 47432 for Hudson Six
- Use 47433 for Hudson Special & Deluxe 8 |
| 45015 | Rear Drum Assy. | - Use 45225 for Hudson Custom 8 |
| 47445 | Rear Drum | - Use 47431 for Terraplane |
| 47446 | Rear Drum | - Use 47432 f or Hudson Six
- Use 47433 for Hudson Special & Deluxe 8 |
| 45278 | Rear Drum | - Use 45225 for Hudson Custom 8 |

WHEEL HUBS
AND DRUMS

Parts Prices and Specifications Bulletin No. 12, 46819 Air Cleaner is shown as carrying a list price of \$2.75.

Please cancel this item, and in its place substitute 48652 Air Cleaner, which carries, net prices only.

A typing error also occurs in this same bulletin, 35028 Piston ring should read 35026 Piston ring.

CORRECTION

STABILIZER

All 1935 Cars which leave the factory with Axleflex are also equipped with the rear spring Stabilizer.

A kit is available through Service for application to any 1934 or 1935 Hudson or Terraplane. The kit includes the torsion bar, mounting brackets, arms and all attaching parts, also instructions for making the installation.

LIST PRICE

HA	47989	Rear Spring Stabilizer Kit	\$7.00
----	-------	----------------------------	--------

SUBSTITUTION
DISCONTINUED

On orders for 62855 Drive Gear and 62859 Drive Pinion (5-6/10 to 1) we have been substituting 63346 Gear and 63447 Pinion (5-1/11 to 1). This substitution will no longer be made and in the future these parts will be available at the following list prices:

BX	62855	Drive Gear - 5-6/10 to 1	6.50
BX	68859	Drive Pinion - 5-6/10 to 1	3.50
BX	63346	Drive Gear - 5-1/11 to 1	6.50
BX	63347	Drive Pinion - 5-1/11 to 1	3.50

P. E. Jones

Supervisor,
Parts Specifications Division
Service Department

HUDSON MOTOR CAR COMPANY

PARTS PRICES AND PARTS SPECIFICATIONS

1935 SERIES BULLETINS

No. 18

Date 6/20/35

Form 8103

Subject

TO ALL DEALERS:

The following list prices on Service Parts are effective immediately.

SERVICE PARTS
PRICES

<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>LIST PRICE</u>
7189	Rear Window Finish Moulding Screw	.01
17912	Folding Top Pillar Bottom W./Seal Screw	.01
40950	Tie Rod Stud and Washer Assembly	.45
40953	Tie Rod Stud Bearing	.15
40956	Tie Rod Stud Dust Washer	.05
43565	R/A Dr. Gear 3-8/9 to 1 Ratio	6.50
46656	R/A Differential Carrier and Gear Set Assembly 3-8/9:1	45.00
46657	R/A Drive Gear and Pinion Assembly (matched)	9.75
46658	R/A Pinion 3-8/9:1	3.50
46894	Steering Gear Shaft Roller Tooth Assembly L.H.D.	5.50
46895	Steering Gear Shaft Roller Tooth Assembly R.H.D.	6.50
46900	Steering Gear Worm Bearing Adjusting Ring	.65
46913	Radio Control Tube	.20
47565	Ground Strap Assembly	.15
47574	Radio Capacitor (Relay)	.48
47689	Light Switch to Service Light Switch Wire Assembly	.10
48233	Brake Double End Lever Pivot Bolt and Bracket Assembly	1.25
48251	Power Unit Intake Cover & Elbow Assembly	2.00
48336	Rear Axle Wheel Bearing Adjustment Cap Assembly	1.00
48337	R/A Wheel Bearing Adjustment Cap. Assembly	1.00
48339	Rear Axle Wheel Bearing Oil Seal	.35
48340	Rear Axle Wheel Bearing Adjustment Cap Oil Seal	.40
48341	Rear Axle Drive Shaft Oil Seal Assembly	.35
48342	Rear Axle Drive Shaft Oil Seal Assembly	.35
48343	Rear Axle Drive Pinion Oil Seal	.80
48398	Hand Brake Cable End Swivel Assembly	.50
48511	Electric Hand Selector Switch Base and Wires Assembly	3.65
48611	Intake Manifold Assembly	3.25
48612	Intake Manifold Assembly	3.75
48617	Steering Gear Comp. (R.H.D.) (Gray Steering Wheel)	27.50
48618	Steering Gear Comp. (R.H.D.) (Tan Steering Wheel)	27.50
48621	Dimmer Switch	1.00
48654	Carburetor Air Cleaner Brace	.50
48656	Power Unit Intake Pipe - Long	.80
48657	Power Unit Intake Pipe - Long	.85
48669	R/A Diff. Carrier and Gear Set, Assembly 3 5/9:1	45.00
48670	R/A Drive Gear and Pinion Assembly (matched) 3-5/9:1	9.75
48671	R/A Drive Gear 3-5/9:1	6.50
48672	R/A Drive Pinion 3-5/9:1	3.50
48673	Transmission Shift Rail Lock Ball Spring Cap	.20
48674	Transmission Shift Rail Lock Plunger	.10

(OVER)

<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>LIST PRICE</u>
49675	Transmission Shift Rail Lock Rod	10
48676	Transmission Shift Rail Lock Rod Sleeve	.05
48677	Transmission Shift Rail Lock Rod Link	.35
48678	Transmission Shift Rail Lock Rod Link Guide	.75
48679	Transmission Shift Rail Lock Rod Guide Shim - Thin	.01
48680	Transmission Shift Rail Lock Rod Link Guide Shim - Thick	.01
48685	Clutch Shifter Yoke Shaft and Lever Assembly	1.25
48687	Clutch Shifter Yoke Shaft Coupling Lever Assembly - L.H.D.	1.25
48688	Clutch Shifter Yoke Shaft Coupling Lever Assembly - R.H.D.	1.25
48691	Clutch Shifter Yoke Shaft Trans. Lock Operating Lever (Low & Rev.)	.40
48704	Electric Hand Lower Switch and Wire Assembly	4.25
48706	Electric Hand Cross Shift Diaphragm Rod Guard	.10
48708	Electric Hand Selector Valve Assembly	18.20
48709	Electric Hand Selector Valve Body Assembly	5.65
48711	Electric Hand Selector Valve Plunger Assembly	1.60
48712	Electric Hand Selector Valve Plunger Assembly	.55
48713	Electric Hand Selector Valve Plunger Disc.	.20
48715	Electric Hand Selector Valve Plunger Spring	.03
48719	Electric Hand Selector Valve Cover Plate Assembly	.85
48723	Transmission Speed Gear 3-5/9:1	2.50
48724	Transmission Speed Pinion 3-5/9:1	1.75
48725	Electric Hand Selector Valve to Cylinder Tube Assembly	.35
48727	Electric Hand Selector Valve to Cylinder Tube Assembly	.45
48729	Electric Hand Valve Solenoid Assembly	2.00
48736	Electric Hand Valve Solenoid Cover	.15
48737	Electric Hand Selector Valve Solenoid Cover Bolt	.10
48738	Electric Hand Selector Valve Solenoid Cover Bolt Gasket	.02
48739	Electric Hand Selector Valve Solenoid Housing Washer	.02
48740	Electric Hand Selector Valve Solenoid Retainer	.30
48741	Electric Hand Selector Valve Solenoid Retainer Gasket	.03
48745	Electric Hand Main Contact Shift Block Assembly	.60
48751	Radio Antenna Kit (Service)	5.00
48752	Radio Antenna Kit (Service)	5.00
48757	Radio Antenna Insulator	.05
48759	Radio Antenna Clip - Cadmium	.05
48760	Radio Antenna Anchor Clip	.05
48761.	Radio Kit (service)	49.95
48762	Radio kit (service)	49.95
46763	Radio Ground Strap) Assembly	.10
46765	Radio Antenna Choke	1.25
48766	Shock Absorber Piston Pressure Relief Valve Assembly - Rear	.75
48767	Shock Absorber Piston Pressure Relief Valve Assembly - L. Rear	.75
48768	Shock Absorber Piston Rear	.60
48769	Shock Absorber Piston Metering Spacer - R e a r	.05
48770	Shock Absorber Piston Intake Valve - Rear	.10
48771	Shock Absorber Piston Intake Valve Spring - Rear	.10
48772	Shock Absorber Piston Support Washer - Rear	.03
48786	Rear Shock Absorber Assembly	6.50
48787	Rear Shock Absorber Assembly	6.50
48790	Rear Shock Absorber Piston	.30
48791	Rear Shock Absorber Piston	.30

(OVER)

<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>LIST PRICE</u>
43797	Front Shock Absorber Assembly	5.50
48798	Front Shock Absorber Assembly	5.50
48820	Carburetor Air Cleaner Intake Pipe Hole Plug	.05
48823	Shock Absorber Piston Pressure Relief Valve Rear	.75
48824	Shock Absorber Piston Pressure Relief Valve Rear	.75
48825	Shock Absorber Piston Pressure Relief Valve Rear	.75
48826	Shock Absorber Piston Pressure Relief Valve Rear	.75
48854	Transmission Shifter Shift Yoke & Lever Assembly	3.25
48855	Transmission Interlock Kit	2.50
48873	Wheel Finish Disc	3.00
62855	Ring Gear	6.50
62859	Pinion	3.50
71290	Clutch Control Link Clevis	.10
71483	Trunk Lid Look Bolt - Lid Half	.02
71484	Trunk Lid Lock Bolt Trunk Half (Cad)	.02
71555	Rear Curtain Light Frame Screw	.02
71570	Selector Valve Stop Plate Screw	.01
71577	R/A Drive Shaft Nut	.10
71587	Selector Switch Housing Steering Column Cap Screw	.01
71588	Selector Switch Housing Steering Column Cap Screw	.01
71589	Selector Switch Cap Screw	.01
100214	Window Regulator Assembly	2.35
100215	Window Regulator Assembly	2.35
100580	Tail Lamp Wire Assembly	.75
100915	Body Header Trim Rail Bolt Nut	.02
109252	Body Front Look Pillar Assembly - R.H.	1.25
109253	Body Front Look Pillar Assembly - L.H.	1.25
109377	W/S Cleaner Blade	.65
109430	Door Wing Cradle Channel and Roller Assembly	.75
109548	Upper Hinge Folding Top Pivot Bracket - R.H.	1.50
109549	Upper Hinge Folding Top Pivot Bracket - L.H.	1.50
109868	Windshield Finish Moulding Joint Cover - Upper	.30
109874	Body Lock Pillar Weatherstrip Ret. - R.H.	1.00
109875	Body Lock Pillar Weatherstrip Ret. - L.H.	1.00
109877	Folding Pillar Weatherstrip Retainer	.95
109878	Hinge Pillar Trim Retainer Assembly - R.H.	.10
109879	Hinge Pillar Trim Retainer Assembly - L.H.	.10
109888	Rear Panel Bolt Tacking Strip - R.H.	1.00
109889	Rear Panel Bolt Tacking Strip - L.H.	1.00
109892	Top Front Header Rail	1.25
109896	Top Front Header Rail Weatherstrip	.20
109897	Top Front Header Rail Weatherstrip End	.10
109898	Top Front Corner Bracket - R.H.	1.25
109899	Top Front Corner Bracket - R.H.	1.25
109900	Folding Top Pillar Bottom Weatherseal - R.H.	.15
109901	Folding Top Pillar Bottom Weatherseal - L.H.	.15
111761	Rear Curtain Glass Grame - Outer	1.50
111762	Rear Curtain Glass Retainer	.50
111814	Header Rail End W/Strip Plate	.20
111912	Trunk Lid Lock Bolt Washer	.01
112410	Rear Compartment Door Hinge Bracket	.02

(Over)

<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>LIST PRICE</u>
112486	Rear Tire Carrier Assembly Comp.	2.25
112488	Rear Tire Carrier Assembly Comp. (Wood Wheel)	2.25
112489	Rear Tire Carrier Assembly Comp. (Wire Wheel)	2.25
112492	Door Assembly - R.H. - Prime	25.00
	- Lacquer	30.00
112493	Door Assembly - L.H. - Prime	25.00
	- Lacquer	30.00
113200	Front Seat Cushion Comp.	20.00
113201	Front Seat Back Comp.	20.00
113551	Assist Strap Assembly	1.25
113658	Front Door Trimboard Complete - R.H.	5.00
113659	Front Door Trimboard Complete - L.H.	5.00
113946	Rear Seat Back Complete	17.50
113948	Rear Seat Cushion Complete	17.50
114128	Dash Lining Pad. - Center	.20
114129	Dash Lining Pad - Sides	.55
114192	Trunk Floor to Seat Back Bracket	.10
114263	Quarter Trim Protector Panel R.H.	3.50
114264	Quarter Trim Protector Panel Assembly - L.H.	3.50
114476	Headlamp Lens	.90
114512	Bonnet Top Panel Assembly - R.H. - Prime	5.00
	- Lacquer	6.25
114513	Bonnet Top Panel Assembly - R.H. - Prime	5.00
	- Lacquer	6.25
114514	Bonnet Top Panel Assembly - R.H. - Prime	6.25
	- Lacquer	7.50
114515	Bonnet Top Panel Assembly - R.H. - Prime	6.25
	- Lacquer	7.50
114616	Tail Larnp and License Bracket Assembly	.50
114617	Tail Larnp and License Bracket Assembly	.50
114640	Rear Compartment Door Lock Striker Support	.20
114668	Gas Tank Gauge Floor Cutout Cover Trimboard Assembly	.10
114669	Gas Tank Gauge Floor Cutout Cover Trimboard Assembly	.10
114692	Headlamp Reflector Assembly	3.00
114694	Headlamp Reflector Assembly (with Parking Lamp Bulb)	2.50
114695	Headlamp Reflector Assembly (without Parking Lamp Bulb)	2.00
114727	Rear Fender Assembly - L.H. - Enamel	9.00
114763	Rear Seat Cushion Spring	5.00
114771	Instrument Panel As Receiver Tray & Cover Assy. (Peroba)	.90
114804	Trunk Lining Trimboard Assembly	1.00
114805	Front Seat Cushion Spring	5.00
114806	Trunk Lining Trimboard Assembly	1.00
114818	Headlamp to Prop. Arm Cushion	.05
114821	Rear Curtain Light Frame Inner	2.25
114822	Rear Curtain Light Frame Outer	2.25
114824	Instrument Mounting Panel	1.50
114847	Rear Window Shim - Upper	.30
114848	Rear Window Shim - Lower	.30
114849	Door Window Belt W/Strip - Inner	.20
114859	Trunk Lid Reinf. - Lacquer	1.50
114859	Trunk Lid Reinf. - Prime or Enamel	1.00

(OVER)

PAR1.12 340.		DESCRIPTION- LIST PRICE
114865	Tire Cover Drum Side Plate Assembly - Lacquer	4.75
114865	Tire Cover Drum Side Plate Assembly - Prime	3.50
114873	Rear r Fender Welt	.45
111875	Door Lock Bolt Spring Retainer Clip	02
114876	Rear Floor Mat - L.H.D.	3.50
114377	Rear Floor Mat - R.H.D.	3.00
114880	Front Door Assembly - R. H. - Lacquer	30.00
	- Prime	25.00
114881	Front Door Assembly - L.H. - Lacquer	30.00
	- Prime	25.00
114884	Front Door Assembly - R. H. - Lacquer	30.00
114884	Front Door Assembly - L.H. - Prime	25.00
114885	Front Door Assembly - L.H. - Lacquer	30.00
114885	'Front Door Assembly - L.H. - Prime	25.00
114888	Front Fender Well Spader Block	.15
114892	Instrument Panel Ash Receiver Tray and Cover Assembly	.75
114893	Rear Quarter and Rear Door Ash Receiver Assembly	.80
114958	Front Door Lock Pillar Channel & Bracket Assembly - R.H.	.30
114959	Front Door Lock Pillar Channel & Bracket Assembly - L.H.	.30
114960	Front Door Lock Pillar Channel & Bracket Assembly Comp. R.H.	1.25
114961	Front Door Lock Pillar Channel & Bracket Assembly Comp. L.H.	1.25
114964	Front Door Lock Pillar Channel Belt Brace Assembly R.H.	.10
114965	Front Door Lock Pillar Channel Belt Brace Assembly L. H.	.10
114968	Front Door Hinge Pillar Glass Run and Channel Assembly - R.H.	.40
114969	Front Door Hinge Pillar Glass Run and Channel Assembly - L.H.	.40
114970	Front Door Hinge Pillar Glass Run Lower	.25
114971	Front Door Lock Pillar Glass Run Lower	.25
114972	Door Glass Rest Channel Assembly - R.H.	1.00
114973	Door Glass Rest Channel Assembly - L.H.	1.00
114976	Door Glass Rest Channel Assembly - R.H.	.90
114977	Door Glass Rest Channel Assembly - L.H.	.90
114992	Door Glass -to Rest Channel Weatherseal - R.H.	.20
114993	Door Glass -to Rest Channel Weatherseal - R.H..	.20
114994	Front Door Glass to Rest Channel Weatherseal - R.H.	.15
114995	Front Door Glass to Rest Channel Weatherseal - L.H.	.15
114998	Trunk Lining Trimboard	.60
115268	Rear Compartment Side Finish Panel - R.H.	.15
115269	Rear Compartment Side Finish Panel - L.H.	.15
115270	Rear Compartment Side Finish Panel - R.H.	.15
115271	Rear Compartment Side Finish Panel - L.H.	.15
115272	Rear Compartment Side Finish Panel - R.H..	.30
115273	Rear Compartment Side Finish Panel - L.H.	.30
115292	Side Header Trimboard and Trim Assembly - R.H.	2.50
115293	Side Header Trimboard and Trim Assembly - L.H.	2.50
115330	Body Side Header W/L. Retainer	.10
115331	Rear Hinge Pillar W/L Retainer	.05
115336	Rear Hinge Pillar W/L. Retainer	.05
115369	Windshield Header Trimboard Assembly	3.00
115370	Side Header Trimboard Assembly - R.H.	5.50
115371	Side Header Trimboard Assembly - L.H.	5.50

(OVER)

SERVICE PARTS
PRICES

- 6 -

<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>LIST PRICE</u>
115376	Upper Quarter Trimboard Assembly - R.H.	4.50
115377	Upper Quarter Trimboard Assembly - L.H.	4.50
115401	Assist Strap Assembly	2.00
115412	Front Door Trimboard Comp. - R. H.	5.50
115413	Front Door Trimboard Comp. - R.L.	5.50
115416	Front Door Trimboard Comp. - R.H.	5.50
115417	Front Door Trimboard Comp. - L.H.	5.50
115420	Rear Comp. & Trunk Side Finish Panel - R.H.	.35
115421	Rear Comp. & Trunk Side Finish Panel - L.H.	.35
115422	Rear Comp. & Trunk Side Finish Panel - R.H.	.30
115423	Rear Comp. & Trunk Side Finish Panel - L.H.	.30
115424	Rear Comp. & Trunk Side Finish Panel - R.H.	.50
115425	Rear Comp. & Trunk Side Finish Panel - R.H.	.50
115429	Front Seat Back Spring	1.50
115430	Front Seat Cushion Spring	3.25
115431	Front Seat Adjustment Handle Assembly	1.00
115433	Trunk Lock Hasp. Lock & Key Assembly	1.25
115434	Trunk Lock Hasp. Pin	.05
115435	Trunk Lock Dog	.05
115436	Trunk Lock Dog Pin	.05
115437	Trunk Look Dog Spring	.25
115527	Dual Windshield Cleaner Idler Shaft Collar	.15
115528	Dual Windshield Cleaner Idler Shaft Collar Gasket	.01
115529	Dual Windshield Cleaner Idler Shaft Assembly	1.25
115606	Tire Cover Hub Cap Spring Clip	.02
115616	Folding Seat Back Support - R.H.	.65
119617	Folding Seat Back Support - L.H.	.65
115636	W/S Opening Drain Tube	.10
115654	Rear Fender Pin. Plate Rubber Welt	.15
115655	Rear Fender Pin. Plate Rubber Welt	.15
115663	Windshield. Frame Clip	.10
115664	Windshield Frame Clip	.10
115698	Front Fender Support & Reinforcement Assembly - R.H.	2.00
115699	Front Fender Support & Reinforcement Assembly - L.H.	2.00
115704	Front Door Window Belt W/Strip Assembly - Inner	.25
115705	Front Door Window Belt W/Strip Assembly - Inner	.20
115706	Rear Door Window Belt W/Strip Assembly - Inner	.20
115707	Quarter Window Belt W/Strip Assembly	.20
115749	Door Handle Lock Bolt Spring	.02
115750	Luggage Carrier Bracket Assembly - R.H.	1.25
115751	Luggage Carrier Bracket Assembly - L.H.	1.25
115801	Luggage Carrier Bracket - L.H.	.30
115846	Luggage Carrier Knurled Handle Clamping Screw Assembly	.65
115847	Luggage Carrier U Clamp Assembly	.15
115848	Luggage Carrier U Clamp Spacer	.10

P. E. Jones

Supervisor,
 Parts Specifications Division
 Service Department

HUDSON MOTOR CAR COMPANY
PARTS PRICES AND PARTS SPECIFICATIONS
1935 SERIES BULLETINS

Form 8103

No. 19

Date 7/2/35

Subject

TO ALL DEALERS:

Trunk LID locks for 1935 Trunk Models with any desired key number in the series way now be obtained through Service. This is of benefit in cases where it is necessary to replace one lock only and will allow the key number of the new lock to match that of the old. These may be obtained by ordering under the following part numbers only:

BO 114188 LIC LOCK ASSEMBLY - R.H. - lid half (Specify key number)

BO 114189 LIC LOCK ASSEMBLY - L.,H. - lid half (Specify key number)

On page 44 of the Dec. 1933 Chassis Parts Book, 42736 Gasoline Tank Assembly is listed as being used on all model K Sedans.

This tank - 42736 - was used on all K Special Sedans and Standard Sedans after Car No. 366871. The Standard Sedans before this car number used the Coach tank - 40263.

On page 49 of the Dec. 1933 Chassis Parts Book, 101616 Rear Splash Guard is listed as being used on all Model K Sedans.

This splash guard - 101616 - was used on all K Special Sedans and Standard Sedans and Standard Sedans after Car No. 366871. The Standard Sedans before this car number used the Coach Splash Guard - 100407.

On page 21 of the 1935 Body Parts Book, the following items should be marked to indicate that they are NOT used on the Terraplane Special 2 Passenger Coupe.

- 101878 Rear Window Regulator Assembly
- 18218 Rear Window Regulator bolt
- 86272 Rear Window Regulator bolt washer
- 107979 Rear Window Regulator Handle Assembly

TRUNK LOCKS

CORRECTION

(OVER)

CORRECTION

On page 154 of the 1935 Chassis Parts Book, cancel the following items, as they are not used.

- C 112496 Radiator shell finish moulding - R.H.
- C 112497 Radiator shell finish moulding - L.H.

NUMERICAL
PRICE LIST

Please note the following corrections on the Numerical Parts Price List.

- 31498 after 31593 should read 31598
- 33101 after 33009 should read 33010
- 36524 after 33524 should read 33525
- 35384 after 33524 should read 35385
- 45112 and 45114 after 45410 should read 410412 and 45414
- 81302 after 86297 should read 86302

96692 Side Lamp - Complete - R.H., priced at \$.25
should be \$5.25

- 35382 priced at \$.40 should be C \$.40
- 39058 priced at .50 should be C .50
- 39059 priced at C .75 should be .75
- 48086 priced at .25 should be .05

P. E. Jones

Supervisor,
Parts Specifications Division
Service Department

HUDSON MOTOR CAR COMPANY

PARTS PRICES AND PARTS SPECIFICATIONS

1935 SERIES BULLETINS

No. 21
 Date 8/26/35
 Subject

Form 8103

TO ALL DEALERS:

The cap for the Windshield Wiper Auxiliary Arm has been redesigned. The now type cap is provided with stops which limit the extreme movement of blade and prevent it from becoming loose and dropping off when blown violently to one side.

	<u>List</u>	<u>Dealer Net</u>
BO 115872 Windshield Cleaner Aux. Arm Cap	.35	.23

- - - - -

Please make following corrections and additions on pages 31 and 32 of the December 1933 Terraplane Chassis Parts Book.

Following parts used to K Car No. 366144

Part No.	Description	X	KU	KT
42240	TRANSMISSION ASSEMBLY	1		
42117	MAIN DRIVE GEAR ASSEMBLY	1		
40095	Mainshaf t	1		
40096	Mainshaft thrust washer	1		
42118	MAINSHAFT INTERMEDIATE GEAR ASSEMBLY	1		
40098	Mainshaft low and reverse gear retainer	2		
42124	Countershaft drive gear	1		
42121	Countershaft intermediate gear	1		

Following parts used after K Car No. 366144

42089	TRANSMISSION ASSEMBLY	1	1	1
42102	MIA111 DRIVE GEAR ASSEMBLY	1	1	1
42918	Mainshaf t	1	1	1
42619	Mainshaft thrust washer	1	1	1
42104	MAINSHAFT INTERMEDIATE GEAR ASSEMBLY	1	1	1
43618	Mainshaft low and reverse gear retainer	2	2	2
42110	Countershaft drive gear	1	1	1
42111	Countershaft intermediate gear	1	1	1

- - - - -

On page 28 of the November 1934 Chassis Parts Book, 42895 Cylinder Head Stud is listed in one place as being 5 13/32" long, and in another as 4 13/32" long, The latter is an error; the correct length of this stud being 5 13/32".

(OVER)

AUXILIARY
ARM CAP

CORRECTION

CORRECTION

In Parts and Specifications Bulletin No. 19 a typing error occurs under the NUMERICAL PRICE LIST.

35382 should be changed to 35482.

A total of 493 1935 Hudson Eight cars were equipped with a special clutch which used a driving plate made of steel without torsion springs, the plate being riveted directly to the hub.

In case replacement of clutch or driving plate becomes necessary the regular Clutch Assembly 45141 or Driving plate Complete 45143 should be used. Other parts are identical with the standard clutch. Cars the special clutch are listed below.

--

Hudson Special Eight	- 546105 to 546673	(No exceptions)
Hudson DeLuxe Eight	- 553005 to 553073	(Exception 553015)
Hudson Spec. 8 - Long W/B	- 57691 to 57799	(Exceptions 57703- - 57704-57709-57710)
Hudson DeLuxe 8 - Long W/B	- 58554 to 58631	(Exception 58570)

--

Hudson Spec. Eight	- 546892 to 546932	(No exceptions)
Hudson DeLuxe Eight	- 553137 to 553142	(No exceptions)
Hudson Spec. 8 - Long W/B	- 57936 to 57954	(No exceptions)
Hudson DeLuxe 8 - Long W/B	- 58743 to 58758	(No exceptions)

Please make the following addition on page 7 of your 1935 Commercial Car Supplement.

- A 112011 RADIATOR SHELL ASSEMBLY - painted
One used on Utility Coach
- A 108925 RADIATOR SHELL ASSEMBLY - painted
One used on Panel, Cab and Cab Pick up.

P. E. Jones

Supervisor,
Parts Specification Division
Service Department

HUDSON MOTOR CAR COMPANY
PARTS PRICES AND PARTS SPECIFICATIONS
1935 SERIES BULLETINS

No. 22

Date 8/23/35

Form 8103

Subject

TO ALL DEALERS:

On Page 3 of the 1935 Chassis Parts Book are listed seven code words for parts wire orders or in reference to parts orders. These are not dictionary words, being purely arbitrary arrangements of letters, and as each word consists of six or more letters it is subject to a charge for two words by the telegraph companies. Only the leniency of these companies has prevented a more wide spread observance of the rule that such words be limited to five letters.

To avoid any difficulty of this nature, these words are being replaced with five letter words and in addition three new code words are being released to denote meanings which could not previously be expressed by a single word.

-
- WUPAH - Ship to me (us) by express
 - WUPEL - Ship by express to
 - WUPIP - Ship to me (us) by freight
 - WUPMU - Ship to me (us) by parcel post
 - WUPOW - Ship to me (us) by parcel post special delivery
 - WUPRY - Ship to me (us) by air mail
 - WUPTA - Ship to me (us) by by air express
 - WURCI - When and how did you ship parts called for in my (our) telegram of
 - WUREX - When and how will you ship parts called for In my (our) telegram of
 - WUROV - When and how will you ship parts called for in my (our) letter of
-

P. E. Jones,
Supervisor,
Parts Specifications Division
Service Department.

WIRE CODE

HUDSON MOTOR CAR COMPANY
PARTS PRICES AND PARTS SPECIFICATIONS
1935 SERIES BULLETINS

No. 24

Date 11/11/35

Form 8103

Subject

TO ALL MASTER DEALERS:

INDEX OF 1935 SERIES PARTS PRICES AND SPECIFICATIONS BULLETINS

<u>NO.</u>	<u>DATE</u>	<u>SUBJECT</u>
1	11/23/34	Announcement 1934 Chassis Parts Book, Second Edition.
2	12/17/34	Water Pump Packing.
3	1/ 8/35	Monroe Shock Absorber Valves - Starting Part Numbers Electric Hand Cross Shift Switch Change.
4	1/22/35	Steering Wheel Substitutions - Correction 1933 Parts Book.
5	1/22/35	Packaged Parts.
6	2/14/35	Radio Service Manual - 1935 Chassis Parts Book - Check Straps,
7	2/19/35	Brake Lining.
8	5/ 6/35	Spring Details - Explanation of Car Serial Numbers.
9	3/27/35	Clutch Vacuum Control Cables - Parts Books Corrections.
10	4/ 3/35	1935 Parts Book Revisions - Brakes - Hand Brake - Drag Link - Springs.
10-A	6/ 7/35	1935 Parts Book Revisions - Battery - Generator - Differential - Drive Shaft - Wheel Bearings - Clutch.
10-B	6/14/35	1935 Parts Book Revisions - Hard Brake - Frame - Throttle Control - Radiator - Coil - Switches.
10-C	7/ 2/35	1935 Parts Book Revisions - Carburetor and Fuel Pump - Clutch Vacuum Control - Wiring - Generator.
10-D	7/19/35	1935 Parts Book Revisions - Engine Mounting - Cylinder Head Studs - Intake Manifold - Timing Gears - Tail Pipe.
10-E	7/30/35	Parts Book Revisions - Manifold Gaskets - Springs - Battery - Radio Antenna.
10-F	7/30 /35	Parts Book Revisions -Springs - Frame - Coil - Radio and Antenna.
11	4/ 4/35	1935 Parts Price List.
12	4/18/35	Parts Price Changes.
13	5/ 1/35	Painted Parts - Terraplane Special Coach Passenger Seat - Parts Book Corrections.
14	5 /27/35	Parts Price Changes
15	6/ 7/35	Confidential Net Price List - 1935 Body Parts Book.
16	6/10/35	Parts Price Changes.
17	6/17/35	Wheel Hubs and Drums - Stabilizer Kit - Drive Gear and Pinion Substitution Discontinued.
18	6/20/35	Parts Price Changes.
19	7/ 2/35	Locks - Corrections to Parts Books.
20	8/19/35	Parts Price Changes.
21	8/25/35	Windshield Cleaner - Parts Book Corrections - Special Clutch.
22	8/23/35	New Wire Code Words
23	9/11/35	Stocking Transmission Parts

P. E. Jones,

Supervisor,
Parts Specification Division,
Service Department